

Product discontinuation notification (PDN)

Title / short description	Discontinuation Low-Runners
Affected article category	Terminal blocks
Change category	Discontinuation
Change number	IBE260015-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation due to portfolio optimization

Detailed description of the change

Discontinuation due to portfolio streamlining.

Identifying characteristics

Attached article list

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-07-31
Effective date (EOP)	2027-04-30	End of Service (EOSR)	-
End of Sales (EOS)	2027-04-30		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IBE260015-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
3060487	UTTB 2,5/2P-PV BU			3060377	UTTB 2,5/2P-PV
1914823	HCC 4-CLIP				
3031309	ST 2,5-QUATTRO/2P-D				
3212444	PTTB 1,5/S/2P BK				
1027883	PTS 1,5/S-3PV/3P				
3061897	PP-H 2,5/24				
3061733	PP-H 6/ 1-R OG				
3043912	SC 2,5/ 6 X82				
1170812	NS 35/ 7,5 BW UNPERF 1000MM				
1277647	NS 35/15 BW LPERF 1000MM				
1037088	PTTBS 2,5 BN			3209604	PTTBS 2,5
3208198	PT 1,5/S-QUATTRO-LA 24 RD				
3210280	PT 2,5-QUATTRO-LA 24 RD				
1054011	DP-CLIPFIX 35-5				
3049440	HV M5/1-VS 3				
3049644	HV M12/1-VS 3				
1067276	DP-HV M12/1 NFF				
1033193	UTT 2,5-2MT-R250/O-U				
3048564	PS-8/2,3MM RD				
3060500	UT 2,5-TWIN/1P BU				
0790620	OTTA 6 YE			0790433	OTTA 6
0804505	CLIPFIX 35/WU				
0803772	NS 35/ 7.5 930MM				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;
3060487;UTTB 2
1914823;HCC 4-CLIP;;;;;27141190;
3031309;ST 2
3212444;PTTB 1
1027883;PTS 1
3061897;PP-H 2
3061733;PP-H 6/ 1-R OG;;;;;27250306;
3043912;SC 2
1170812;NS 35/ 7
1277647;NS 35/15 BW LPERF 1000MM;;;;;27400602;
1037088;PTTBS 2
3208198;PT 1
3210280;PT 2
1054011;DP-CLIPFIX 35-5;;;;;
3049440;HV M5/1-VS 3;;;;;27141190;
3049644;HV M12/1-VS 3;;;;;27141190;
1067276;DP-HV M12/1 NFF;;;;;27250301;
1033193;UTT 2
3048564;PS-8/2
3060500;UT 2
0790620;OTTA 6 YE;;;0790433;OTTA 6;27250101;
0804505;CLIPFIX 35/WU;;;;;27250302;
0803772;NS 35/ 7.5 930MM;;;;;27400602;

5/2P-PV BU;;;3060377;UTTB 2

5/2P-PV;27250102;

5-QUATTRO/2P-D;;;;;27250117;

5/S/2P BK;;;;;27250117;

5/S-3PV/3P;;;;;27250102;

5/24;;;;;27250306;

5/ 6 X82;;;;;27141106;

5 BW UNPERF 1000MM;;;;;27400602;

5 BN;;;3209604;PTTBS 2

5;27250102;

5/S-QUATTRO-LA 24 RD;;;;;27250101;

5-QUATTRO-LA 24 RD;;;;;27250101;

5-2MT-R250/O-U;;;;;

3MM RD;;;;;27250304;

5-TWIN/1P BU;;;;;27250117;

PCN/PDN Number	Customer Number	Company Name	Street
IBE260015	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	0804505

Phoenix Contact Item Designation (changed/discontinued article)

CLIPFIX 35/WU

Phoenix Contact Article-Nr. (customer specific)

8191413

Phoenix Contact Article Designation (customer specific)
CANRIG-PUSH-IN-RAIL

Report Date Substitute Item
08.06.2026

Replacement Product Designation