



Product Change Notification

Current Date: 06-Aug-2026

TE Connectivity

Product Change Notification: P-26-030969

PCN Date: 03-AUG-26

Customer: Shanghai TTI Electronics Co Ltd (1405773)

Location: Shanghai

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Multiple Parts Numbers

Description of Changes

To improve the fit and retention of the ISL during shipping, prior to terminal installation a lower alignment rib has been added in the housing that prevents the ISL from over rotation. The housings 2x ISL guiding side walls have also been tightened 0.10 mm per side to reduce overall ISL displacement and movement during transit.

Other attachments:

[Presentation](#)

Reason for Changes:

Product improvement. Male Housing X-2482012-X and ISL X-2482016-X fit and alignment has been improved to eliminate any ISL shifting during shipping, prior to terminal installation.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

07-AUG-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-2479934-2	NO						
2479934-1	NO						



Product Change Notification

Current Date: 06-Aug-2026

TE Connectivity

Product Change Notification: P-26-030969

PCN Date: 03-AUG-26

Customer: Shanghai TTI Electronics Co Ltd (3064990)

Location: Shanghai

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Multiple Parts Numbers

Description of Changes

To improve the fit and retention of the ISL during shipping, prior to terminal installation a lower alignment rib has been added in the housing that prevents the ISL from over rotation. The housings 2x ISL guiding side walls have also been tightened 0.10 mm per side to reduce overall ISL displacement and movement during transit.

Other attachments:

[Presentation](#)

Reason for Changes:

Product improvement. Male Housing X-2482012-X and ISL X-2482016-X fit and alignment has been improved to eliminate any ISL shifting during shipping, prior to terminal installation.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

07-AUG-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-2479934-2	NO						
2479934-1	NO						