Littelfuse®

Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

Issue Date: Oct 30th, 2026

Dear Valued Customer,
This PCN 0660 notice is to inform you that, due to the discontinuation of one or more components used in the manufacturing of the products listed below, Littelfuse will discontinue the affected part number.

Description of the Change:

Littelfuse will discontinue the affected part number and place them into obsolescence.

Reason for The Change:

One or more components required to manufacture the affected product have been discontinued by our supply base and are no longer available. As a result, Littelfuse is unable to ensure the continued production of the affected part number.

Affected Part Number: 00681300

Effective Date of the Change:

Effective immediately

What You Need to Do:

No action is required from you. Please note that no further orders can be supported for the affected part number.

To verify current inventory availability or discuss your requirements, please contact your usual Customer Service or Inside Sales representative.

Littelfuse regrets any inconvenience this situation may cause and appreciates your understanding and continued support.

Sincerely,

Cristal Furini

Product Manager
Commercial Vehicle Products

Part numbers related to PCN C0660

LF Part Number
00681300