

Product change notification (PCN)

Title / short description	TCP 32DC - UL approval added
Affected article category	Protective devices
Change category	Approval, Marking
Change number	CCL260008-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

TCP 32DC - UL approval added

Detailed description of the change

The TCP 32DC circuit breakers are UL-listed in accordance with UL1077. Excluding item 1499947-TCP 32DC/40A F.

As part of this change, the UKCA logo will be removed from all items.

Identifying characteristics

Increased V/C on packaging label

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-11-30	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PCN-CCL260008-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1499963	TCP 32DC/5A M	00	01		
1499965	TCP 32DC/6A M	00	01		
1499966	TCP 32DC/7,5A M	00	01		
1499967	TCP 32DC/10A M	00	01		
1499968	TCP 32DC/15A M	00	01		
1499969	TCP 32DC/20A M	00	01		
1499972	TCP 32DC/25A M	00	01		
1499987	TCP 32DC/30A M	00	01		
1499939	TCP 32DC/5A F	00	01		
1499940	TCP 32DC/6A F	00	01		
1499941	TCP 32DC/7,5A F	00	01		
1499942	TCP 32DC/10A F	00	01		
1499943	TCP 32DC/15A F	00	01		
1499944	TCP 32DC/20A F	00	01		
1499945	TCP 32DC/25A F	00	01		
1499946	TCP 32DC/30A F	00	01		
1499947	TCP 32DC/40A F	00	01		

PCN/PDN Number	Customer Number	Company Name	Street
CCL260008	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	1499963

Phoenix Contact Item Designation (changed/discontinued article)

TCP 32DC/5A M

Quantity Sales 2024

0

Quantity Sales 2025	Quantity Sales 2026	Quantity Orders 2026	Report Date	Substitute Item
200	300	200	22.09.2026	

Replacement Product Designation

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1499963;TCP 32DC/5A M;00;01;;;27140401;

1499965;TCP 32DC/6A M;00;01;;;27140401;

1499966;TCP 32DC/7

1499967;TCP 32DC/10A M;00;01;;;27140401;

1499968;TCP 32DC/15A M;00;01;;;27140401;

1499969;TCP 32DC/20A M;00;01;;;27140401;

1499972;TCP 32DC/25A M;00;01;;;27140401;

1499987;TCP 32DC/30A M;00;01;;;27140401;

1499939;TCP 32DC/5A F;00;01;;;27140401;

1499940;TCP 32DC/6A F;00;01;;;27140401;

1499941;TCP 32DC/7

1499942;TCP 32DC/10A F;00;01;;;27140401;

1499943;TCP 32DC/15A F;00;01;;;27140401;

1499944;TCP 32DC/20A F;00;01;;;27140401;

1499945;TCP 32DC/25A F;00;01;;;27140401;

1499946;TCP 32DC/30A F;00;01;;;27140401;

1499947;TCP 32DC/40A F;00;01;;;27140401;

5A M;00;01;;;27140401;

5A F;00;01;;;27140401;