

Product change notification (PCN)

Title / short description	Change of screw surface finish
Affected article category	PCB terminal blocks and PCB connectors
Change category	Material
Change number	CAA260138-00
Reason for PCN/PDN Revision	

Purpose/objective of the change
Change of screw surface finish

Detailed description of the change

We are changing the surface finish of the screws from a custom specification to a standard zinc plating. This ensures that the screws and the associated mounting brackets have the same surface finish. This change secures continued product availability. The affected items are listed in this PCN. The change has no impact on form, fit, function, or approvals.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-09-24	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☒ Others | | |
- Ensure delivery capability.

Attachments

- Material_list.csv
- PCN-CAA260138-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1837298	KGS-PC 4/10				
1805123	KGS-MSTB 2,5/ 9 BK				
1837353	KGS-PC 4/ 6-F				
1783821	KGS-MSTB 2,5/13				
1837340	KGG-PC 4/ 5-F				
1837337	KGG-PC 4/ 4-F				
1837379	KGS-PC 4/ 8-F				
1805657	KGS-MSTB 2,5/24				
1783805	KGS-MSTB 2,5/11				
1764367	KGS-MSTB 2,5/16 BK				
1805602	KGS-MSTB 2,5/19				
1815455	KGS-MSTB 2,5/ 9 BEIGE				
1837311	KGS-PC 4/12				
1805628	KGS-MSTB 2,5/21				
1739127	KGG-MSTB 2,5-ST-SET CFS2				
1837243	KGG-PC 4/ 5				
1837395	KGS-PC 4/10-F				
1742729	KGS-MSTB 2,5/12 BK				
1837285	KGS-PC 4/ 9				
1837230	KGG-PC 4/ 4				
1783834	KGS-MSTB 2,5/14				
1805592	KGS-MSTB 2,5/18				
1823053	KGS-MSTB 2,5/10 BK				
1837405	KGS-PC 4/11-F				
1994830	KGS-PC 4/10-F BK				
1837366	KGS-PC 4/ 7-F				
1805644	KGS-MSTB 2,5/23				
1783847	KGS-MSTB 2,5/15				
1783740	KGS-MSTB 2,5/10				
1703954	KGS-MSTB 2,5/18 BK				
1783818	KGS-MSTB 2,5/12				
1805589	KGS-MSTB 2,5/17				
1783782	KGS-MSTB 2,5/ 9				
1783850	KGS-MSTB 2,5/16				
1783779	KGS-MSTB 2,5/ 8				
1805631	KGS-MSTB 2,5/22				
1925074	KGS-MSTB 2,5/14 BU				
1837269	KGS-PC 4/ 7				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
1805615	KGS-MSTB 2,5/20	old	new		
1837382	KGS-PC 4/ 9-F				
1837418	KGS-PC 4/12-F				
1837256	KGS-PC 4/ 6				
1742716	KGS-MSTB 2,5/20 BK				
1837272	KGS-PC 4/ 8				
1763025	MOTORSTECKER SET SR6-X9				
1803918	KGG-MSTB 2,5/ 7				
1834453	KGG-MC 1,5/13				
1834411	KGG-MC 1,5/ 9				
1834408	KGG-MC 1,5/ 8				
1834385	KGG-MC 1,5/ 6				
1681359	KGG-MSTB 2,5/ 6 BK				
1834440	KGG-MC 1,5/12				
1743524	KGG-PC 4/ 3-F BK				
1834482	KGG-MC 1,5/16				
1119016	KGG-MC 1,5/ 7 CL				
1834398	KGG-MC 1,5/ 7				
1834424	KGG-MC 1,5/10				
1714993	KGG-MC 1,5/ 6 BK				
1837227	KGG-PC 4/ 3				
1803905	KGG-MSTB 2,5/ 6				
1651803	KGG-MSTB 2,5/ 7 GY				
1700996	KGG-MC 1,5/12 BK				
1834479	KGG-MC 1,5/15				
1095607	KGG-MSTB 2,5/ 6 SET				
1834437	KGG-MC 1,5/11				
1850411	MC 1,5 STECKER-SET NZ:X148-CB1				
1713973	KGG-MSTB 2,5/ 7 BK				
1803921	KGG-MSTB 2,5/ 8				
1967867	KGG-MC 1,5/16 BK				
1834466	KGG-MC 1,5/14				
1837324	KGG-PC 4/ 3-F				

Phoenix Contact Art.Nr.;	Phoenix Contact Art.Bez.;	Bemerkung
1837298	;KGS-PC 4/10;	HW/FW alt:
1805123	;KGS-MSTB 2	
1837353	;KGS-PC 4/ 6-F;	HW/FW alt:
1783821	;KGS-MSTB 2	
1837340	;KGG-PC 4/ 5-F;	HW/FW alt:
1837337	;KGG-PC 4/ 4-F;	HW/FW alt:
1837379	;KGS-PC 4/ 8-F;	HW/FW alt:
1805657	;KGS-MSTB 2	
1783805	;KGS-MSTB 2	
1764367	;KGS-MSTB 2	
1805602	;KGS-MSTB 2	
1815455	;KGS-MSTB 2	
1837311	;KGS-PC 4/12;	HW/FW alt:
1805628	;KGS-MSTB 2	
1739127	;KGG-MSTB 2	
1837243	;KGG-PC 4/ 5;	HW/FW alt:
1837395	;KGS-PC 4/10-F;	HW/FW alt:
1742729	;KGS-MSTB 2	
1837285	;KGS-PC 4/ 9;	HW/FW alt:
1837230	;KGG-PC 4/ 4;	HW/FW alt:
1783834	;KGS-MSTB 2	
1805592	;KGS-MSTB 2	
1823053	;KGS-MSTB 2	
1837405	;KGS-PC 4/11-F;	HW/FW alt:
1994830	;KGS-PC 4/10-F BK;	HW/FW alt:
1837366	;KGS-PC 4/ 7-F;	HW/FW alt:
1805644	;KGS-MSTB 2	
1783847	;KGS-MSTB 2	
1783740	;KGS-MSTB 2	
1703954	;KGS-MSTB 2	
1783818	;KGS-MSTB 2	
1805589	;KGS-MSTB 2	
1783782	;KGS-MSTB 2	
1783850	;KGS-MSTB 2	
1783779	;KGS-MSTB 2	
1805631	;KGS-MSTB 2	
1925074	;KGS-MSTB 2	
1837269	;KGS-PC 4/ 7;	HW/FW alt:
1805615	;KGS-MSTB 2	
1837382	;KGS-PC 4/ 9-F;	HW/FW alt:
1837418	;KGS-PC 4/12-F;	HW/FW alt:
1837256	;KGS-PC 4/ 6;	HW/FW alt:
1742716	;KGS-MSTB 2	
1837272	;KGS-PC 4/ 8;	HW/FW alt:
1763025	;MOTORSTECKER SET SR6-X9;	HW/FW alt:
1803918	;KGG-MSTB 2	
1834453	;KGG-MC 1	

1834411	;KGG-MC 1
1834408	;KGG-MC 1
1834385	;KGG-MC 1
1681359	;KGG-MSTB 2
1834440	;KGG-MC 1
1743524	;KGG-PC 4/ 3-F BK;HW/FW alt:
1834482	;KGG-MC 1
1119016	;KGG-MC 1
1834398	;KGG-MC 1
1834424	;KGG-MC 1
1714993	;KGG-MC 1
1837227	;KGG-PC 4/ 3;HW/FW alt:
1803905	;KGG-MSTB 2
1651803	;KGG-MSTB 2
1700996	;KGG-MC 1
1834479	;KGG-MC 1
1095607	;KGG-MSTB 2
1834437	;KGG-MC 1
1850411	;MC 1
1713973	;KGG-MSTB 2
1803921	;KGG-MSTB 2
1967867	;KGG-MC 1
1834466	;KGG-MC 1
1837324	;KGG-PC 4/ 3-F;HW/FW alt:

HW/FW neu:	eCl@ss 13.0: 27460402	
5/ 9 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
5/13;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
5/24;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/11;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/16 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/19;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 9 BEIGE;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
5/21;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5-ST-SET CFS2;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27469090
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
5/12 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
5/14;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/18;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/10 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
5/23;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/15;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/10;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/18 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/12;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/17;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 9;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/16;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 8;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/22;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/14 BU;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
5/20;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27460402	
5/20 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
HW/FW neu:	eCl@ss 13.0: 27469090	
5/ 7;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/13;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402

5/ 9;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 8;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 6;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 6 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/12;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
5/16;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 7 CL;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 7;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/10;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 6 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	
5/ 6;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 7 GY;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460291
5/12 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/15;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 6 SET;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460405
5/11;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5 STECKER-SET NZ:X148-CB1;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27469090
5/ 7 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/ 8;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/16 BK;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
5/14;HW/FW alt:	HW/FW neu:	eCl@ss 13.0: 27460402
HW/FW neu:	eCl@ss 13.0: 27460402	

Kunde;Name 1;Name 2;Name 3;Name 4;Straße;PLZ;Stadt;Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Ihre |

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

49786 ;TTI

Materialnr.;Menge 2024 ST;Menge 2025 ST;Menge 2026 ST;AE 2026 ST

Inc.;;;Ganghoferstraße 34;82216;Maisach;1837353	;KGS-PC 4/ 6-F;PHX1837353;0 ST;;50 ST;50 ST
Inc.;;;Ganghoferstraße 34;82216;Maisach;1783821	;KGS-MSTB 2
Inc.;;;Ganghoferstraße 34;82216;Maisach;1837340	;KGG-PC 4/ 5-F;PHX1837340;350 ST;280 ST;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1837337	;KGG-PC 4/ 4-F;PHX1837337;;100 ST;;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1783805	;KGS-MSTB 2
Inc.;;;Ganghoferstraße 34;82216;Maisach;1783850	;KGS-MSTB 2
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834453	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834408	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834385	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834440	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834398	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1834424	;KGG-MC 1
Inc.;;;Ganghoferstraße 34;82216;Maisach;1837227	;KGG-PC 4/ 3;PHX1837227;;30 ST;30 ST
Inc.;;;Ganghoferstraße 34;82216;Maisach;1803905	;KGG-MSTB 2
Inc.;;;Ganghoferstraße 34;82216;Maisach;1803921	;KGG-MSTB 2
Inc.;;;Ganghoferstraße 34;82216;Maisach;1837324	;KGG-PC 4/ 3-F;PHX1837324;;450 ST;;

3T

5/13;PHX1783821;;10 ST;;

;

5/11;PHX1783805;;10 ST;;

5/16;PHX1783850;50- ST;;

5/13;PHX1834453;;;5.160 ST;5.160 ST

5/ 8;PHX1834408;100 ST;50 ST;90 ST;90 ST

5/ 6;PHX1834385;100- ST;;540 ST;540 ST

5/12;PHX1834440;200 ST;100 ST;100 ST;100 ST

5/ 7;PHX1834398;;;0 ST;10 ST

5/10;PHX1834424;1.390 ST;400 ST;1.980 ST;1.750 ST

5/ 6;PHX1803905;100 ST;;800 ST;800 ST

5/ 8;PHX1803921;40 ST;;50 ST;50 ST

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1837298;KGS-PC 4/10;;;;;27460402;
1805123;KGS-MSTB 2
1837353;KGS-PC 4/ 6-F;;;;;27460402;
1783821;KGS-MSTB 2
1837340;KGG-PC 4/ 5-F;;;;;27460402;
1837337;KGG-PC 4/ 4-F;;;;;27460402;
1837379;KGS-PC 4/ 8-F;;;;;27460402;
1805657;KGS-MSTB 2
1783805;KGS-MSTB 2
1764367;KGS-MSTB 2
1805602;KGS-MSTB 2
1815455;KGS-MSTB 2
1837311;KGS-PC 4/12;;;;;27460402;
1805628;KGS-MSTB 2
1739127;KGG-MSTB 2
1837243;KGG-PC 4/ 5;;;;;27460402;
1837395;KGS-PC 4/10-F;;;;;27460402;
1742729;KGS-MSTB 2
1837285;KGS-PC 4/ 9;;;;;27460402;
1837230;KGG-PC 4/ 4;;;;;27460402;
1783834;KGS-MSTB 2
1805592;KGS-MSTB 2
1823053;KGS-MSTB 2
1837405;KGS-PC 4/11-F;;;;;27460402;
1994830;KGS-PC 4/10-F BK;;;;;27460402;
1837366;KGS-PC 4/ 7-F;;;;;27460402;
1805644;KGS-MSTB 2
1783847;KGS-MSTB 2
1783740;KGS-MSTB 2
1703954;KGS-MSTB 2
1783818;KGS-MSTB 2
1805589;KGS-MSTB 2
1783782;KGS-MSTB 2
1783850;KGS-MSTB 2
1783779;KGS-MSTB 2
1805631;KGS-MSTB 2
1925074;KGS-MSTB 2
1837269;KGS-PC 4/ 7;;;;;27460402;
1805615;KGS-MSTB 2
1837382;KGS-PC 4/ 9-F;;;;;27460402;
1837418;KGS-PC 4/12-F;;;;;27460402;
1837256;KGS-PC 4/ 6;;;;;27460402;
1742716;KGS-MSTB 2
1837272;KGS-PC 4/ 8;;;;;27460402;
1763025;MOTORSTECKER SET SR6-X9;;;;;27469090;
1803918;KGG-MSTB 2
1834453;KGG-MC 1

1834411;KGG-MC 1
1834408;KGG-MC 1
1834385;KGG-MC 1
1681359;KGG-MSTB 2
1834440;KGG-MC 1
1743524;KGG-PC 4/ 3-F BK;;;;;27460402;
1834482;KGG-MC 1
1119016;KGG-MC 1
1834398;KGG-MC 1
1834424;KGG-MC 1
1714993;KGG-MC 1
1837227;KGG-PC 4/ 3;;;;;27460402;
1803905;KGG-MSTB 2
1651803;KGG-MSTB 2
1700996;KGG-MC 1
1834479;KGG-MC 1
1095607;KGG-MSTB 2
1834437;KGG-MC 1
1850411;MC 1
1713973;KGG-MSTB 2
1803921;KGG-MSTB 2
1967867;KGG-MC 1
1834466;KGG-MC 1
1837324;KGG-PC 4/ 3-F;;;;;27460402;

5/ 9 BK,,,,,27460402;

5/13,,,,,27460402;

5/24,,,,,27460402;

5/11,,,,,27460402;

5/16 BK,,,,,27460402;

5/19,,,,,27460402;

5/ 9 BEIGE,,,,,27460402;

5/21,,,,,27460402;

5-ST-SET CFS2,,,,,27469090;

5/12 BK,,,,,27460402;

5/14,,,,,27460402;

5/18,,,,,27460402;

5/10 BK,,,,,27460402;

5/23,,,,,27460402;

5/15,,,,,27460402;

5/10,,,,,27460402;

5/18 BK,,,,,27460402;

5/12,,,,,27460402;

5/17,,,,,27460402;

5/ 9,,,,,27460402;

5/16,,,,,27460402;

5/ 8,,,,,27460402;

5/22,,,,,27460402;

5/14 BU,,,,,27460402;

5/20,,,,,27460402;

5/20 BK,,,,,27460402;

5/ 7,,,,,27460402;

5/13,,,,,27460402;

5/ 9;;;;;27460402;
5/ 8;;;;;27460402;
5/ 6;;;;;27460402;
5/ 6 BK;;;;;27460402;
5/12;;;;;27460402;

5/16;;;;;27460402;
5/ 7 CL;;;;;27460402;
5/ 7;;;;;27460402;
5/10;;;;;27460402;
5/ 6 BK;;;;;27460402;

5/ 6;;;;;27460402;
5/ 7 GY;;;;;27460291;
5/12 BK;;;;;27460402;
5/15;;;;;27460402;
5/ 6 SET;;;;;27460405;
5/11;;;;;27460402;
5 STECKER-SET NZ:X148-CB1;;;;;27469090;
5/ 7 BK;;;;;27460402;
5/ 8;;;;;27460402;
5/16 BK;;;;;27460402;
5/14;;;;;27460402;