

Document Receipt Acknowledgement

Date:
Section:
Name:



Document Number: D06110-A-D7300
Date: Mar. 8, 2023

Attention:

TTI

Product Withdrawal Notice

Part of Muata Power Solution's HP-BMP/HP-FEP Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
This is the official notification that some of our products will be discontinued as detailed below.
Please review this, and approve in writing by Approval Due Date.
Also, please place Last Time Buy Order by the Last Time Order Due Date as needed.
Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata Part Numbers:

Product Type: Part of Muata Power Solution's HP-BMP/HP-FEP Series
Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

Because the parts used in our company products have been discontinued and to low volume sales, production of our company products will be discontinued according to the following schedule.

3. Approval Due: Dec. 29, 2023

Please review this, and reply to Sales for this Notice in writing by Due Date.
In case we do not get any contacts by the Due Date,
we will assume that this Notice with all its contents has been accepted.

4. Product Withdrawal Schedule:

Last Time Order Due (*): Mar. 29, 2024
Last Shipment Date: Sep. 30, 2024

* : Last Time Order is the subject to Minimum Order Quantity and Package Quantity.
Order Cancel and Product Return can be accepted only in the case of quality issue.
Please place Last Time Buy Order by the Last Time Order Due Date as needed.
We cannot receive any orders after Last Time Order Due.

5. Contact Window:

Should you have any questions or concerns,
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.
Murata Power Solutions / Director of Marketing
Bill Smith



Document Number: D06110-A-D7300

Confirmation Letter

TTI

Murata Manufacturing, Co., Ltd.

Product Withdrawal Confirmation

Product Type: Part of Muata Power Solution's HP-BMP/HP-FEP Series

Last Time Order Due: Mar. 29, 2024

Last Shipment Date: Sep. 30, 2024

Product Withdrawal detailed below is

- accepted, and we will not place Last Time Order.
- accepted, and we will place Last Time Order as below.

Last Time Order Schedule:

Last Shipment Schedule:

Comments, Questions, etc.

Signature

Date: (MM, DD, YYYY)

Title:

Name:

Sales History

Please find the list below for the target part numbers which are registered as yours in Murata. (Customer Part Number)

Regardless of the list below, all part numbers shall be the target as far as they are categorized into the Product Type indicated in the Document.

Alternative Part Number: Pin Structure, Electrical Characteristics could be identical to or different from the current product.

Account Number	Customer Name	Customer Part Number	Murata Part Number	Alternative Part Number	Sales Quantity (Unit: pieces)						Memo
					2017FY	2018FY	2019FY	2020FY	2021FY	2022FY till Feb.	
D0970	TTI	MPSDMS-20PC-1-PGL-C	DMS-20PC-1-PGL-C	N/A	0	108	60	0	0	0	
D0970	TTI	MPSIRQ-5/20-T110N-C	IRQ-5/20-T110N-C	N/A	0	0	964	0	390	0	
D0970	TTI	MPSUEI-12/4.2-Q12P-C	UEI-12/4.2-Q12P-C	N/A	60	0	0	0	0	0	
D0970	TTI	MPSUQQ-12/8-Q12P-C	UQQ-12/8-Q12P-C	N/A	0	0	0	0	240	0	
D0970	TTI	MPSUWQ-12/17-Q48N-C	UWQ-12/17-Q48N-C	N/A	0	0	0	0	29	0	
D0970	TTI	MURIRQ-5/20-T110N-C	IRQ-5/20-T110N-C	N/A	0	150	0	0	0	0	
D0975	TTI	MPSD1U3CS-W-850-12HC4SC	D1U3CS-W-850-12-HC4SC	N/A	207	90	311	98	101	0	
D0975	TTI	MPSUEI-12/4.2-Q12P-C	UEI-12/4.2-Q12P-C	N/A	0	60	0	0	0	0	
D7320	TTI	MPSIRQ-5/20-T110N-C	IRQ-5/20-T110N-C	N/A	0	0	0	0	29	30	

Part Number List

Please find the list below for the target part numbers which are registered as yours in Murata. (Customer Part Number)
Regardless of the list below, all part numbers shall be the target as far as they are categorized into the Product Type indicated in the Document.
Alternative Part Number: Pin Structure, Electrical Characteristics could be identical to or different from the current product.

Customer Part Number	Murata Part Number	Alternative Part Number	Sales Quantity (Unit: pieces)						Memo
			2017FY	2018FY	2019FY	2020FY	2021FY	2022FY till Feb.	
MPSD1U3CS-W-850-12HC4SC	D1U3CS-W-850-12-HC4SC	N/A	207	90	311	98	101	0	
MPSDMS-20PC-1-PGL-C	DMS-20PC-1-PGL-C	N/A	0	108	60	0	0	0	
MPSIRQ-5/20-T110N-C	IRQ-5/20-T110N-C	N/A	0	0	964	0	419	30	
MPSUEI-12/4.2-Q12P-C	UEI-12/4.2-Q12P-C	N/A	60	60	0	0	0	0	
MPSUQQ-12/8-Q12P-C	UQQ-12/8-Q12P-C	N/A	0	0	0	0	240	0	
MPSUWQ-12/17-Q48N-C	UWQ-12/17-Q48N-C	N/A	0	0	0	0	29	0	
MURIRQ-5/20-T110N-C	IRQ-5/20-T110N-C	N/A	0	150	0	0	0	0	

Target Part Number List

Murata Part Number	Replacement
1 BEI15-050-Q12P-C	No Direct Replacement
2 BEI15-050-Q48N-C	No Direct Replacement
3 BEI15-050-Q48XHL1-C	No Direct Replacement
4 BEI15-120-Q48N-C	No Direct Replacement
5 BEI15-120-Q48NLI1-C	No Direct Replacement
6 BEI15-150-Q48N-C	No Direct Replacement
7 BEI15-150-Q48N-C-CIS	No Direct Replacement
8 BPM15-050-Q48N-C	No Direct Replacement
9 BWR-12/415-D12A-C	No Direct Replacement
10 BWR-12/415-D48A-C	No Direct Replacement
11 BWR-5/1500-D24A-C	No Direct Replacement
12 DAE0133V2N1BC	No Direct Replacement
13 DAE0133V2N1BRC	No Direct Replacement
14 DAE0133V2N2BC	No Direct Replacement
15 DAE0133V2N2BRC	No Direct Replacement
16 DAE0133V2NBRC	No Direct Replacement
17 DAE0133V2P1BC	No Direct Replacement
18 DAE0133V2P1BRC	No Direct Replacement
19 DAE0133V2P2BC	No Direct Replacement
20 DAE0133V2P2BRC	No Direct Replacement
21 DAE0133V2PBC	No Direct Replacement
22 DAE0133V2PBC	No Direct Replacement
23 DAQ0150V2N1BC	No Direct Replacement
24 DAQ0150V2PBC	No Direct Replacement
25 DBE0125V2N1BC	No Direct Replacement
26 DBE0125V2N1BSC	No Direct Replacement
27 DBE0125V2N1C	No Direct Replacement
28 DBE0125V2N1SC	No Direct Replacement
29 DBE0125V2N2BC	No Direct Replacement
30 DBE0125V2N2BSC	No Direct Replacement
31 DBE0125V2N2C	No Direct Replacement
32 DBE0125V2N2SC	No Direct Replacement
33 DBE0125V2NBRC	No Direct Replacement
34 DBE0125V2NBSRC	No Direct Replacement
35 DBE0125V2NC	No Direct Replacement
36 DBE0125V2NSC	No Direct Replacement
37 DBE0125V2P1BC	No Direct Replacement
38 DBE0125V2P1BSC	No Direct Replacement
39 DBE0125V2P1C	No Direct Replacement
40 DBE0125V2P1SC	No Direct Replacement
41 DBE0125V2P2BC	No Direct Replacement
42 DBE0125V2P2BSC	No Direct Replacement
43 DBE0125V2P2C	No Direct Replacement
44 DBE0125V2P2SC	No Direct Replacement
45 DBE0125V2PBC	No Direct Replacement
46 DBE0125V2PBC	No Direct Replacement
47 DBE0125V2PC	No Direct Replacement
48 DBE0125V2PSC	No Direct Replacement
49 DBE0240V2N1BC	No Direct Replacement
50 DBE0240V2N1C	No Direct Replacement
51 DBE0240V2N2BC	No Direct Replacement
52 DBE0240V2N2C	No Direct Replacement
53 DBE0240V2NC	No Direct Replacement
54 DBE0240V2P1BC	No Direct Replacement
55 DBE0240V2P1C	No Direct Replacement
56 DBE0240V2P2BC	No Direct Replacement
57 DBE0240V2P2C	No Direct Replacement
58 DBE0240V2PBC	No Direct Replacement
59 DBE0240V2PC	No Direct Replacement
60 DBE0340V2N1BC	No Direct Replacement
61 DBE0340V2N1C	No Direct Replacement
62 DBE0340V2N2BC	No Direct Replacement
63 DBE0340V2N2C	No Direct Replacement
64 DBE0340V2NBC	No Direct Replacement
65 DBE0340V2NC	No Direct Replacement
66 DBE0340V2P1BC	No Direct Replacement
67 DBE0340V2P1C	No Direct Replacement
68 DBE0340V2P2BC	No Direct Replacement
69 DBE0340V2P2C	No Direct Replacement
70 DBE0340V2PBC	No Direct Replacement

Murata Part Number	Replacement
71 DBE0340V2PC	No Direct Replacement
72 DBQ0135V2N1BSC	No Direct Replacement
73 DBQ0135V2N2BSC	No Direct Replacement
74 DBQ0135V2N2C	No Direct Replacement
75 DBQ0135V2NBC	No Direct Replacement
76 DBQ0135V2NBSA1C	No Direct Replacement
77 DBQ0135V2NBSC	No Direct Replacement
78 DBQ0135V2NC	No Direct Replacement
79 DBQ0135V2NSC	No Direct Replacement
80 DBQ0135V2P2BC	No Direct Replacement
81 DBQ0135V2P2BSC	No Direct Replacement
82 DBQ0135V2P2C	No Direct Replacement
83 DBQ0135V2PBC	No Direct Replacement
84 DBQ0135V2PBC	No Direct Replacement
85 DBQ0135V2PC	No Direct Replacement
86 DBQ0135V2PSC	No Direct Replacement
87 DBQ0260V2N2BC	No Direct Replacement
88 DBQ0260V2N2C	No Direct Replacement
89 DBQ0260V2NBC	No Direct Replacement
90 DBQ0260V2NC	No Direct Replacement
91 DBQ0260V2P2BC	No Direct Replacement
92 DBQ0260V2P2C	No Direct Replacement
93 DBQ0260V2PBC	No Direct Replacement
94 DBQ0260V2PC	No Direct Replacement
95 DBQ0360V2N2BC	No Direct Replacement
96 DBQ0360V2N2C	No Direct Replacement
97 DBQ0360V2NBC	No Direct Replacement
98 DBQ0360V2NC	No Direct Replacement
99 DBQ0360V2P2BC	No Direct Replacement
100 DBQ0360V2P2C	No Direct Replacement
101 DBQ0360V2PBC	No Direct Replacement
102 DBQ0360V2PC	No Direct Replacement
103 DCE0133V2N1BC	No Direct Replacement
104 DCE0133V2N1BRC	No Direct Replacement
105 DCE0133V2N1BSC	No Direct Replacement
106 DCE0133V2N1BSRC	No Direct Replacement
107 DCE0133V2N2BC	No Direct Replacement
108 DCE0133V2N2BRC	No Direct Replacement
109 DCE0133V2N2BSC	No Direct Replacement
110 DCE0133V2N2BSRC	No Direct Replacement
111 DCE0133V2NBRC	No Direct Replacement
112 DCE0133V2NBSC	No Direct Replacement
113 DCE0133V2NBSRC	No Direct Replacement
114 DCE0133V2P1BC	No Direct Replacement
115 DCE0133V2P1BRC	No Direct Replacement
116 DCE0133V2P1BSC	No Direct Replacement
117 DCE0133V2P1BSRC	No Direct Replacement
118 DCE0133V2P2BC	No Direct Replacement
119 DCE0133V2P2BRC	No Direct Replacement
120 DCE0133V2P2BSC	No Direct Replacement
121 DCE0133V2P2BSRC	No Direct Replacement
122 DCE0133V2PBC	No Direct Replacement
123 DCE0133V2PBRC	No Direct Replacement
124 DCE0133V2PBC	No Direct Replacement
125 DCE0133V2PBSRC	No Direct Replacement
126 DCM20-1-DC5-G-C	No Direct Replacement
127 DCQ0150V2NBSRC	No Direct Replacement
128 DCQ0150V2PBC	No Direct Replacement
129 DCQ0150V2PBC	No Direct Replacement
130 DMS-20PC-1-LM-GF-C	No Direct Replacement
131 DMS-20PC-1-PGL-C	No Direct Replacement
132 DSE0133V2N1BC	No Direct Replacement
133 DSE0133V2N1BRC	No Direct Replacement
134 DSE0133V2N1BSC	No Direct Replacement
135 DSE0133V2N1BSRC	No Direct Replacement
136 DSE0133V2N2BC	No Direct Replacement
137 DSE0133V2N2BRC	No Direct Replacement
138 DSE0133V2N2BSC	No Direct Replacement
139 DSE0133V2N2BSRC	No Direct Replacement
140 DSE0133V2NBPGHC	No Direct Replacement

弊社対象品番一覧

Murata Part Number	Replacement	
141	DSE0133V2NBRC	No Direct Replacement
142	DSE0133V2NBSRC	No Direct Replacement
143	DSE0133V2P1BC	No Direct Replacement
144	DSE0133V2P1BRC	No Direct Replacement
145	DSE0133V2P1BSC	No Direct Replacement
146	DSE0133V2P1BSRC	No Direct Replacement
147	DSE0133V2P2BC	No Direct Replacement
148	DSE0133V2P2BRC	No Direct Replacement
149	DSE0133V2P2BSC	No Direct Replacement
150	DSE0133V2P2BSRC	No Direct Replacement
151	DSE0133V2PBC	No Direct Replacement
152	DSE0133V2PBRC	No Direct Replacement
153	DSE0133V2PBSRC	No Direct Replacement
154	DSM-31335-C	No Direct Replacement
155	DSQ0150V2N1BSC	No Direct Replacement
156	DSQ0150V2N1BSRC	No Direct Replacement
157	DSQ0150V2N2BSC	No Direct Replacement
158	DSQ0150V2PBC	No Direct Replacement
159	DSQ0150V2PBSC	No Direct Replacement
160	DVE0125V2N1BC	No Direct Replacement
161	DVE0125V2N1BSC	No Direct Replacement
162	DVE0125V2N1C	No Direct Replacement
163	DVE0125V2N1SC	No Direct Replacement
164	DVE0125V2N2BSC	No Direct Replacement
165	DVE0125V2N2C	No Direct Replacement
166	DVE0125V2N2SC	No Direct Replacement
167	DVE0125V2NBRC	No Direct Replacement
168	DVE0125V2NBSC	No Direct Replacement
169	DVE0125V2NBSRC	No Direct Replacement
170	DVE0125V2NRC	No Direct Replacement
171	DVE0125V2NSC	No Direct Replacement
172	DVE0125V2P1BC	No Direct Replacement
173	DVE0125V2P1BSC	No Direct Replacement
174	DVE0125V2P1SC	No Direct Replacement
175	DVE0125V2P2BC	No Direct Replacement
176	DVE0125V2P2BSC	No Direct Replacement
177	DVE0125V2P2C	No Direct Replacement
178	DVE0125V2P2SC	No Direct Replacement
179	DVE0125V2PBC	No Direct Replacement
180	DVE0125V2PBSC	No Direct Replacement
181	DVE0125V2PC	No Direct Replacement
182	DVE0125V2PSC	No Direct Replacement
183	DVE0240V2N1BC	No Direct Replacement
184	DVE0240V2N1C	No Direct Replacement
185	DVE0240V2N2BC	No Direct Replacement
186	DVE0240V2N2C	No Direct Replacement
187	DVE0240V2NBC	No Direct Replacement
188	DVE0240V2NC	No Direct Replacement
189	DVE0240V2P1BC	No Direct Replacement
190	DVE0240V2P1C	No Direct Replacement
191	DVE0240V2P2BC	No Direct Replacement
192	DVE0240V2P2C	No Direct Replacement
193	DVE0240V2PBC	No Direct Replacement
194	DVE0240V2PC	No Direct Replacement
195	DVE0340V2N1BC	No Direct Replacement
196	DVE0340V2N1C	No Direct Replacement
197	DVE0340V2N2BC	No Direct Replacement
198	DVE0340V2N2C	No Direct Replacement
199	DVE0340V2NBC	No Direct Replacement
200	DVE0340V2NC	No Direct Replacement
201	DVE0340V2P1BC	No Direct Replacement
202	DVE0340V2P1C	No Direct Replacement
203	DVE0340V2P2BC	No Direct Replacement
204	DVE0340V2P2C	No Direct Replacement
205	DVE0340V2PBC	No Direct Replacement
206	DVE0340V2PC	No Direct Replacement
207	DVQ0135V2NBSC	No Direct Replacement
208	DVQ0135V2NC	No Direct Replacement
209	DVQ0135V2NSC	No Direct Replacement
210	DVQ0135V2PBC	No Direct Replacement

Murata Part Number	Replacement	
211	DVQ0135V2PBSC	No Direct Replacement
212	DVQ0135V2PC	No Direct Replacement
213	DVQ0135V2PSC	No Direct Replacement
214	DVQ0260V2NBC	No Direct Replacement
215	DVQ0260V2NC	No Direct Replacement
216	DVQ0260V2PBC	No Direct Replacement
217	DVQ0260V2PC	No Direct Replacement
218	DVQ0360V2N1BC	No Direct Replacement
219	DVQ0360V2NBC	No Direct Replacement
220	DVQ0360V2NC	No Direct Replacement
221	DVQ0360V2PBC	No Direct Replacement
222	DVQ0360V2PC	No Direct Replacement
223	IRE-12/8.3-T110N-C	No Direct Replacement
224	IRE-12/8.3-T110NF-C	No Direct Replacement
225	IRE-12/8.3-T110P-C	No Direct Replacement
226	IRE-12/8.3-T110PF-C	No Direct Replacement
227	IRE-24/4.2-T110N-C	No Direct Replacement
228	IRE-24/4.2-T110NF-C	No Direct Replacement
229	IRE-24/4.2-T110P-C	No Direct Replacement
230	IRE-24/4.2-T110PF-C	No Direct Replacement
231	IRE-5/20-T110N-C	No Direct Replacement
232	IRE-5/20-T110NF-C	No Direct Replacement
233	IRE-5/20-T110P-C	No Direct Replacement
234	IRE-5/20-T110PF-C	No Direct Replacement
235	IRH-12/12.5-T110N-C	No Direct Replacement
236	IRH-12/12.5-T110NF-C	No Direct Replacement
237	IRH-12/12.5-T110NVF-C	No Direct Replacement
238	IRH-12/12.5-T110P-C	No Direct Replacement
239	IRH-12/12.5-T110PF-C	No Direct Replacement
240	IRH-12/12.5-T110PVF-C	No Direct Replacement
241	IRH-24/6.3-T110N-C	No Direct Replacement
242	IRH-24/6.3-T110NF-C	No Direct Replacement
243	IRH-24/6.3-T110NVF-C	No Direct Replacement
244	IRH-24/6.3-T110P-C	No Direct Replacement
245	IRH-24/6.3-T110PF-C	No Direct Replacement
246	IRH-24/6.3-T110PVF-C	No Direct Replacement
247	IRH-5/30-T110N-C	No Direct Replacement
248	IRH-5/30-T110NF-C	No Direct Replacement
249	IRH-5/30-T110NVF-C	No Direct Replacement
250	IRH-5/30-T110P-C	No Direct Replacement
251	IRH-5/30-T110PF-C	No Direct Replacement
252	IRH-5/30-T110PVF-C	No Direct Replacement
253	IRQ-12/8.3-T110N-C	No Direct Replacement
254	IRQ-12/8.3-T110NVF-C	No Direct Replacement
255	IRQ-12/8.3-T110P-C	No Direct Replacement
256	IRQ-12/8.3-T110PF-C	No Direct Replacement
257	IRQ-24/4.2-T110NVF-C	No Direct Replacement
258	IRQ-24/4.2-T110P-C	No Direct Replacement
259	IRQ-24/4.2-T110PVF-C	No Direct Replacement
260	IRQ-5/20-T110N-C	No Direct Replacement
261	IRQ-5/20-T110NF-C	No Direct Replacement
262	IRQ-5/20-T110NVF-C	No Direct Replacement
263	IRQ-5/20-T110P-C	No Direct Replacement
264	IRQ-5/20-T110PF-C	No Direct Replacement
265	IRQ-5/20-T110PVF-C	No Direct Replacement
266	PAE-29/3-D48NB3-C	No Direct Replacement
267	PAE-29/3-D48NBL1-C	No Direct Replacement
268	PAH-28/12.5-D24NB1-C	No Direct Replacement
269	PAH-28/12.5-D24NB1L2-C	No Direct Replacement
270	PAH-28/12.5-D24NBH-C	No Direct Replacement
271	PAH-28/12.5-D24NBHL2-C	No Direct Replacement
272	PAH-28/12.5-D24PB1-C	No Direct Replacement
273	PAH-28/12.5-D24PB1L2-C	No Direct Replacement
274	PAH-28/12.5-D24PBH-C	No Direct Replacement
275	PAH-28/12.5-D48NB1-C	No Direct Replacement
276	PAH-28/12.5-D48NB1L2-C	No Direct Replacement
277	PAH-28/12.5-D48NB1VTL-C	No Direct Replacement
278	PAH-28/16-D48NB1-C	No Direct Replacement
279	PAH-28/16-D48NB1L2-C	No Direct Replacement
280	PAH-28/16-D48NB1VTL-C	No Direct Replacement

弊社対象品番一覧

Murata Part Number	Replacement
281 PAH-28/16-D48NBH-C	No Direct Replacement
282 PAH-28/16-D48NBL2-C	No Direct Replacement
283 PAH-28/16-D48PB1-C	No Direct Replacement
284 PAH-28/16-D48PB-C	No Direct Replacement
285 PAH-28/16-D48PBH-C	No Direct Replacement
286 PAH-53/8.5-D48NB1-C	No Direct Replacement
287 PAH-53/8.5-D48NBL2-C	No Direct Replacement
288 PAH-53/8.5-D48PB1-C	No Direct Replacement
289 PAH-53/8.5-D48PB-C	No Direct Replacement
290 RBE-12/20-D48NBH-C	No Direct Replacement
291 RBE-12/20-D48NH-C	No Direct Replacement
292 SPM15-033-Q48-C	No Direct Replacement
293 SPM15-033-Q48P-C	No Direct Replacement
294 SPM15-050-Q48P-C	No Direct Replacement
295 SPM15-120-Q48P-C	No Direct Replacement
296 SPM15-150-Q48P-C	No Direct Replacement
297 SPM25-033-D48-C	No Direct Replacement
298 SPM25-033-D48N-C	No Direct Replacement
299 SPM25-033-D48P-C	No Direct Replacement
300 SPM25-050-D48-C	No Direct Replacement
301 SPM25-050-D48PL1-C	No Direct Replacement
302 SPM25-120-D48P-C	No Direct Replacement
303 UEE-12/12.5-D48NBH-C	No Direct Replacement
304 UEE-12/12.5-D48NBL2-C	No Direct Replacement
305 UEI-12/4.2-Q12P-C	No Direct Replacement
306 UEI-12/5-Q48N-C	No Direct Replacement
307 UEI15-033-Q48PH-C	No Direct Replacement
308 UEI15-050-Q48PH-C	No Direct Replacement
309 UEI15-120-Q48NL1-C	No Direct Replacement
310 UEI15-150-Q48NL2-C	No Direct Replacement
311 UEI25-050-D48NL1-C	No Direct Replacement
312 UEI25-120-D48NL2-C	No Direct Replacement
313 UEI25-120-D48NM-C	No Direct Replacement
314 UEI-3.3/15-Q12N-C	No Direct Replacement
315 UEI-3.3/15-Q12NR-C	No Direct Replacement
316 UEI-3.3/15-Q12NRH-C	No Direct Replacement
317 UEI-3.3/15-Q12P-C	No Direct Replacement
318 UEI-3.3/15-Q12PR-C	No Direct Replacement
319 UEI30-120-Q12PL1-C	No Direct Replacement
320 UEI30-120-Q12PL2-C	No Direct Replacement
321 ULS121501C	No Direct Replacement
322 ULS121501ZC	No Direct Replacement
323 ULT050301C	No Direct Replacement
324 ULT-1.8/12.5-D48N-C	No Direct Replacement
325 ULT-1.8/12.5-D48P-C	No Direct Replacement
326 ULT-3.3/7.5-D48NBL2-C	No Direct Replacement
327 UQQ-12/8-Q12PB9-C	No Direct Replacement
328 UQQ-12/8-Q12PBL2-C	No Direct Replacement
329 UQQ-12/8-Q12P-C	No Direct Replacement
330 UQQ-24/4-Q12PBH-C	No Direct Replacement
331 UQQ-24/4-Q12P-C	No Direct Replacement
332 UQQ-3.3/25-Q12P-C	No Direct Replacement
333 UQQ-3.3/25-Q48NB-C	No Direct Replacement
334 UVQ-12/8-D24N-C	No Direct Replacement
335 UWE-12/10-Q12N-C	No Direct Replacement
336 UWE-12/10-Q12NL1-C	No Direct Replacement
337 UWE-12/6-Q12NB-C	No Direct Replacement
338 UWE-12/6-Q12N-C	No Direct Replacement
339 UWE-12/6-Q12PL2-C	No Direct Replacement
340 UWE-12/6-Q48NB-C-CIS	No Direct Replacement
341 UWE-12/6-Q48NBL1-C-CIS	No Direct Replacement
342 UWE-12/6-Q48NBL2-C	No Direct Replacement
343 UWE-24/3-Q12PBH-C	No Direct Replacement
344 UWE-24/3-Q12PBL1-C	No Direct Replacement
345 UWE-24/5-Q12P-C	No Direct Replacement
346 UWE-3.3/20-Q12NB-C	No Direct Replacement
347 UWE-3.3/20-Q12P-C	No Direct Replacement
348 UWE-3.3/20-Q48NBL2-C	No Direct Replacement
349 UWE-31337-C	No Direct Replacement
350 UWE-5/15-Q12NB-C	No Direct Replacement

Murata Part Number	Replacement
351 UWE-5/20-Q48NBL2-C	No Direct Replacement
352 UWE-5/24-Q12N-C	No Direct Replacement
353 UWE-5/24-Q12P-C	No Direct Replacement
354 UWQ-12/17-Q48N-C	No Direct Replacement
355 UWS-12/4.5-Q12N-C	No Direct Replacement
356 UWS-12/4.5-Q48NH-C	No Direct Replacement
357 UWS-12/4.5-Q48NL1-C	No Direct Replacement
358 UWS-12/4.5-Q48NL2-C	No Direct Replacement
359 UWS-12/4.5-Q48P-C	No Direct Replacement
360 UWS-12/4.5-Q48PH-C	No Direct Replacement
361 UWS-12/4.5-Q48PM-C	No Direct Replacement
362 UWS-12/7.5-Q48N-C	No Direct Replacement
363 UWS-15/3-Q12N-C	No Direct Replacement
364 UWS-24/2-Q12N-C	No Direct Replacement
365 UWS-24/2-Q48N-C	No Direct Replacement
366 UWS-24/2-Q48P-C	No Direct Replacement
367 UWS-3.3/15-Q12N-C	No Direct Replacement
368 UWS-3.3/15-Q48NH-C	No Direct Replacement
369 UWS-3.3/15-Q48P-C	No Direct Replacement
370 UWS-3.3/15-Q48PH-C	No Direct Replacement
371 UWS-3.3/15-Q48PM-C	No Direct Replacement
372 UWS-48/1-Q48P-C	No Direct Replacement
373 UWS-5/10-Q12N-C	No Direct Replacement
374 UWS-5/10-Q48NH-C	No Direct Replacement
375 UWS-5/10-Q48NHL2-C	No Direct Replacement
376 UWS-5/10-Q48PH-C	No Direct Replacement
377 UWS-5/10-Q48PM-C	No Direct Replacement
378 D1U2-D-400-12-HA4C	No Direct Replacement
379 D1U3CS-D-1600-12-HC4EC	No Direct Replacement
380 D1U3CS-W-1300F-12-HA4EC	No Direct Replacement
381 D1U3CS-W-1300F-12-HC4EC	No Direct Replacement
382 D1U3CS-W-1300F-12-HC4VC	No Direct Replacement
383 D1U3CS-W-850-12-HC45C	No Direct Replacement
384 D1U4-W-1600-54-HB3MC	No Direct Replacement
385 D1U4-W-1600-54-HB4C	No Direct Replacement
386 D1U4-W-1600-54-HB4MC	No Direct Replacement
387 D1U54-BLANK3	No Direct Replacement
388 D1U54P-W-1500-12-HC3TC-GR	No Direct Replacement
389 D1U54P-W-1500-12-HC4TC-GR	No Direct Replacement
390 D1U54P-W-650-12-HB3BC-INT	No Direct Replacement
391 D1U74T-W-1600-12-HB4C	No Direct Replacement
392 D1U-W-2000-12-HA2FHC	No Direct Replacement
393 FFI1917-1500-12D	No Direct Replacement
394 INTC1961-800-12T	No Direct Replacement
395 INTC1962-800-12T	No Direct Replacement
396 M1896	No Direct Replacement
397 MVAC250-12AF	No Direct Replacement
398 MVAC400-24AFJT	No Direct Replacement
399 MVAC400-48AFD	No Direct Replacement
400 S1U-3X-16-A-48-RC-AEM	No Direct Replacement