

June 19, 2026

Dear customers

Subject: Notice of discontinuation of production

We would like to take this opportunity to extend our appreciation for the business relationship between our companies and your continuous support to our organization.

We would like to inform you that we have decided to discontinue production of the aluminum electrolytic capacitors listed in the table below. Please refer to the details of the discontinuation and potential replacements. We would appreciate your understanding.

1. Products discontinuation

#	Type	Series	Overview	Note
1	Lead	UBT	125degC, 3,000 / 5,000H	100V / All Sizes except ϕ 8
2	Lead	UBW	135degC, 2,000 / 3,000H	100V / All Sizes except ϕ 8
3	Lead	UBX	150degC, 1,000 / 2,000H	80V / All Sizes
4	Chip	UCD	105degC, 5,000H	100V / 47uF
5	Lead	UPJ	105degC, 5,000H	100V / Selected ratings
6	Lead	UPM	105degC, 5,000H	100V / Selected ratings
7	Lead	UPW	105degC, 3,000H	100V / 15uF

Notice: This applies only to catalog items. Please refer to the attached document for part numbers.

2. Replacements for discontinued products

Please see the attached document.

3. Final order date for discontinued products

Until May 31, 2027

4. Last shipping date

Scheduled on May 31, 2028. It depends on production conditions.

5. Reason for changing to discontinuation.

The number of orders for the affected products has been declining in recent years. After considering ways to improve productivity through consolidation and closure, we have decided to officially end production. As a result, the production status will be changed to final order status.

Sincerely yours,
Nichicon Corporation

EOL itemsAlternative items

No	MPN	品番
1	UBT2A101MHD8	UBY2A161MHL
2	UBT2A220MPD8	No replacement
3	UBT2A221MHD8	UBY2A271MHL
4	UBT2A330MPD8	No replacement
5	UBT2A331MHD8	UBY2A391MHL
6	UBT2A470MPD8	No replacement
7	UBW2A101MHD	UBY2A161MHL
8	UBW2A220MPD	No replacement
9	UBW2A221MHD	UBY2A271MHL
10	UBW2A330MPD	No replacement
11	UBW2A331MHD	UBY2A391MHL
12	UBW2A470MPD	No replacement
13	UBX1K101MHL	UBX2A101MHL
14	UBX1K221MHL	UBX2A221MHL
15	UBX1K330MPL	No replacement
16	UBX1K331MHL	No replacement
17	UBX1K470MPL	No replacement
18	UBX1K471MHL	No replacement
19	UBX1K560MPL	No replacement
20	UBX1K680MPL	No replacement
21	UCD2A470MNJ1MS	UCD2A680MNJ1MS
22	UCD2A470MNQ1MS	UCD2A680MNQ1MS
23	UCD2A470MNS1MS	UCD2A680MNS1MS
24	UPJ2A101MHD6	No replacement
25	UPJ2A121MHD	No replacement
26	UPJ2A270MPD6	No replacement
27	UPJ2A330MPD6	UPW2A330MPD
28	UPJ2A390MPD6	No replacement
29	UPJ2A470MHD6	No replacement
30	UPJ2A470MPD	UPW2A470MPD
31	UPJ2A471MHD	UPW2A471MHD
32	UPJ2A471MHD6	No replacement
33	UPJ2A560MHD6	No replacement
34	UPJ2A560MPD	No replacement
35	UPJ2A680MPD	UPW2A680MPD
36	UPJ2A820MHD6	No replacement
37	UPJ2A820MPD	UPW2A820MPD
38	UPM2A121MHD	No replacement
39	UPM2A221MHD6	UPW2A221MHD
40	UPM2A270MPD6	No replacement
41	UPM2A390MPD6	No replacement
42	UPM2A470MHD6	No replacement
43	UPM2A470MPD	UPW2A470MPD
44	UPM2A471MHD6	No replacement
45	UPM2A560MHD6	No replacement
46	UPM2A680MPD	UPW2A680MPD
47	UPM2A820MPD	UPW2A820MPD
48	UPW2A150MPD	No replacement