

## Product discontinuation notification (PDN)

**Title / short description** Discontinuation due to portfolio streamlining  
**Affected article category** Terminal blocks  
**Change category** Discontinuation  
**Change number** IBE250028-00  
**Reason for PCN/PDN Revision**

**Purpose/objective of the change**  
 Discontinuation

**Detailed description of the change**  
 Due to a lack of demand, we will discontinue the listed articles.

**Identifying characteristics**  
 See attached item list

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	2027-07-31
<b>Effective date (EOP)</b>	2027-04-30	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	2027-04-30		

**Short-term change (< 6 months) or discontinuation (< 12 months), due to:**

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

**Attachments**

- Material\_list.csv
- PDN-IBE250028-00\_EN

**Material list**

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1043624	RT 5-T BDRD			3049039	RT 5-T
3030118	FBS 2-4 GY			3030116	FBS 2-4
3030131	FBS 3-4 GY			3030129	FBS 3-4
3030134	FBS 4-4 GY			3030132	FBS 4-4
3030147	FBS 5-4 GY			3030145	FBS 5-4
3030160	FBS 10-4 GY			3030158	FBS 10-4
3030354	FBS 20-4 GY			3030352	FBS 20-4
3049518	RTO 3			3049013	RT 3
3049615	RTO 3-PE			3049411	RT 3-PE
3049660	RTO 3 BU			3049110	RT 3 BU
3049767	RTO 5 BU			3049123	RT 5 BU
3049835	RTO 3-TC BU			3049110	RT 3 BU
3049851	RTO 5-TC BU			3049123	RT 5 BU
3049864	RTO 8 BU			3049148	RT 8 BU
3049929	RTO 8-TC BU			3049148	RT 8 BU
3049945	RTO 3-TC			3049013	RT 3
3049958	RTO 3-PE-TC			3049411	RT 3-PE
3049974	RTO 5-PE-TC			3049628	RTO 5-PE
3240065	NS 35/15 ZN UNPERF 3000MM			1206586	NS 35/15 ZN UNPERF 2000MM
1346829	HV 1XM8/1 4XM6/1-STL				
1346827	HV 1XM8/1 9XM6/1-STL				
3071081	HV M10/1 M6/1-STL2				
1346749	1XM10/1 NFF-2XM6/2-STL NFF SET				
1346748	2XM10/1 NFF-3XM6/2-STL NFF SET				
3002341	RBO 6-WD			1099418	RBO 6-WD-HC
3205200	DS-QTC 1,5			3205190	D-QTC 1,5-TWIN
3206607	DS-QTC 2,5			3206571	D-QTC 2,5-TWIN
1201455	E/U			1201044	E/1
1227418	E/UK-NS 35 GN			1202577	E/UK-NS 35
1030161	RBO 10-WD			3244614	RBO 10
1053781	W-RBO 16				
1170837	RBOC 10/6-TP DGY				
3049025	W-RT 5				
3212840	PH 1,5/S/12				
3212866	PH 1,5/S/14				
3212879	PH 1,5/S/15				
3209772	PH 2,5/11				
3209808	PH 2,5/14				

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
3050510	D-QTCU 2,5 TWIN				
1172179	NUT WITH WASHER M5 DIN				
1172177	NUT WITH WASHER M6 DIN				
1172181	NUT WITH WASHER M10 DIN				
1172182	NUT WITH WASHER M12 DIN				
1096337	RBO 8 INW			3213137	RBO 8
0790621	OTTA 6-P/P YE			0790404	OTTA 6-P/P

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;  
1043624;RT 5-T BDRD;;;3049039;RT 5-T;;  
3030118;FBS 2-4 GY;;;3030116;FBS 2-4;27250303;  
3030131;FBS 3-4 GY;;;3030129;FBS 3-4;27250303;  
3030134;FBS 4-4 GY;;;3030132;FBS 4-4;27250303;  
3030147;FBS 5-4 GY;;;3030145;FBS 5-4;27250303;  
3030160;FBS 10-4 GY;;;3030158;FBS 10-4;27250303;  
3030354;FBS 20-4 GY;;;3030352;FBS 20-4;27250303;  
3049518;RTO 3;;;3049013;RT 3;27250101;  
3049615;RTO 3-PE;;;3049411;RT 3-PE;27250103;  
3049660;RTO 3 BU;;;3049110;RT 3 BU;27250101;  
3049767;RTO 5 BU;;;3049123;RT 5 BU;27250101;  
3049835;RTO 3-TC BU;;;3049110;RT 3 BU;27250101;  
3049851;RTO 5-TC BU;;;3049123;RT 5 BU;27250101;  
3049864;RTO 8 BU;;;3049148;RT 8 BU;27250101;  
3049929;RTO 8-TC BU;;;3049148;RT 8 BU;27250101;  
3049945;RTO 3-TC;;;3049013;RT 3;27250101;  
3049958;RTO 3-PE-TC;;;3049411;RT 3-PE;27250103;  
3049974;RTO 5-PE-TC;;;3049628;RTO 5-PE;27250103;  
3240065;NS 35/15 ZN UNPERF 3000MM;;;1206586;NS 35/15 ZN UNPERF 2000MM;27400602;  
1346829;HV 1XM8/1 4XM6/1-STL;;;;;27250192;  
1346827;HV 1XM8/1 9XM6/1-STL;;;;;27141190;  
3071081;HV M10/1 M6/1-STL2;;;;;27141190;  
1346749;1XM10/1 NFF-2XM6/2-STL NFF SET;;;;;27250190;  
1346748;2XM10/1 NFF-3XM6/2-STL NFF SET;;;;;27250190;  
3002341;RBO 6-WD;;;1099418;RBO 6-WD-HC;27250190;  
3205200;DS-QTC 1  
3206607;DS-QTC 2  
1201455;E/U;;;1201044;E/1;27250302;  
1227418;E/UK-NS 35 GN;;;1202577;E/UK-NS 35;27250302;  
1030161;RBO 10-WD;;;3244614;RBO 10;27250101;  
1053781;W-RBO 16;;;;;  
1170837;RBOC 10/6-TP DGY;;;;;27460407;  
3049025;W-RT 5;;;;;27141190;  
3212840;PH 1  
3212866;PH 1  
3212879;PH 1  
3209772;PH 2  
3209808;PH 2  
3050510;D-QTCU 2  
1172179;NUT WITH WASHER M5 DIN;;;;;  
1172177;NUT WITH WASHER M6 DIN;;;;;  
1172181;NUT WITH WASHER M10 DIN;;;;;  
1172182;NUT WITH WASHER M12 DIN;;;;;

1096337;RBO 8 INW;;;3213137;RBO 8;;  
0790621;OTTA 6-P/P YE;;;0790404;OTTA 6-P/P;27250101;

5;;;3205190;D-QTC 1 5-TWIN;27250301;  
5;;;3206571;D-QTC 2 5-TWIN;27250301;

5/S/12;;;;;27440202;  
5/S/14;;;;;27440202;  
5/S/15;;;;;27440202;  
5/11;;;;;27440202;  
5/14;;;;;27440202;  
5 TWIN;;;;;27250301;

<b>PCN/PDN Number</b>	<b>Customer Number</b>	<b>Company Name</b>	<b>Street</b>
IBE250028	401641	TTI, INC.	2441 NORTHEAST PKWY

<b>Postcode/Zip Code</b>	<b>City</b>	<b>Phoenix Contact Item-Nr. (changed/discontinued article)</b>
76106	FORT WORTH	3030118

**Phoenix Contact Item Designation (changed/discontinued article)**

FBS 2-4 GY

**Report Date    Substitute Item**

08.06.2026    3030116

**Replacement Product Designation**

FBS 2-4