

Product discontinuation notification (PDN)

Title / short description	Product discontinuation as a part of portfolio streamlining
Affected article category	System cabling for controllers
Change category	Discontinuation
Change number	IDK250010-00
Reason for PCN/PDN Revision	

Purpose/objective of the change
Product discontinuation

Detailed description of the change

The listed items (see item list) will be discontinued. If needed, you may select replacement items from the current portfolio.

Identifying characteristics

See attached item list for discontinued items

Start of Production (SOP)	-	Last Time Delivery (LTD)	2026-10-31
Effective date (EOP)	2025-10-31	End of Service (EOSR)	-
End of Sales (EOS)	2026-04-30		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IDK250010-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2903139	CABLE-DB37F-2IC14/0,4/CS1112				
1037026	CABLE-DB37F-OE/S/200/CS1736				
1486499	CABLE-IC20/OE/0,5M/1500/CS				
1486509	CABLE-IC20/OE/1,5M/1500/CS				
1486546	CABLE-IC20/OE/10,0M/1500/CS				
1486520	CABLE-IC20/OE/3,0M/1500/CS				
1486527	CABLE-IC20/OE/4,0M/1500/CS				
1486543	CABLE-IC20/OE/6,0M/1500/CS				
1486544	CABLE-IC20/OE/8,0M/1500/CS				
1381499	CABLE-IC34/FE/15,0M/VSF				
1486563	CABLE-IC40/OE/0,5M/1500/CS				
1486565	CABLE-IC40/OE/1,0M/1500/CS				
1486877	CABLE-IC40/OE/10,0M/1500/CS				
1486599	CABLE-IC40/OE/3,0M/1500/CS				
1486604	CABLE-IC40/OE/4,0M/1500/CS				
1486873	CABLE-IC40/OE/6,0M/1500/CS				
1486876	CABLE-IC40/OE/8,0M/1500/CS				
1579870	CABLE-IC50/IC50/2,5M/1500/CS				
1646754	CABLE-VIP20/OE/AIO/1,2M/CS2315				
1646750	CABLE-VIP20/OE/DIO/1,2M/CS2315				
2906139	CABLE-VIP50-2IC20/15,0M/CS1445				
2900169	FLKM-2FLK40/PMT/SI/Z/YCS				
5775269	FUSE TR5 SPARE PACKAGE				
1434265	UM-20DIO/SPT/PT/ZF/CS2025				
1579866	UM-2IC14/SC/16R/DO/1CO/1500/CS				
1490672	UM-2IC14/SC/DI/16/F/1500/CS				
1098079	UM-2MK40/20R/NO/NC/ETSP/CS1831				
5774548	UM72-R-24DC/21HC				
1427419	UM-DB25M/16R/DI/AC/CS2204				
1427429	UM-DB25M/16R/DI/CS2204				
2909841	UM-DB37F/15R/CO/DO/CS1657				
1567896	UM-DB37F/32R/DI/CS2307				
1567890	UM-DB37F/32R/DO/CS2307				
1568063	UM-DB37F/AI/CS2307				
1568058	UM-DB37F/DI/CS2307				
1568057	UM-DB37F/GT/CS2307				
2901567	UM-DB37M/16R/DO/CO/J/C300				
1551630	UM-DB37M/DI/32R/F/CS2305				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2908884	UM-EC56F/16/AO/DO/F/CS1633				
2908879	UM-EC56F/16R/CO/DO/F/CS1629				
1587634	UM-FLK20/M/16R/DI/F/CS2303				
1509671	UM-IC10/SC/DO/8R/1CO/CS2214				
1509674	UM-IC10/SC/DO/8R/2CO/CS2214				
1670079	UM-IC14/8R/DO/NO/220V/CS2316				
1670069	UM-IC14/8R/DO/NO/24V/CS2316				
1670000	UM-IC14/AI/4/CS2316				
1670050	UM-IC14/DI/8/CS2316				
1368094	UM-IC14/SC/DO/8R/1CO/DRY/1500				
1670018	UM-IC20/AO/4/CS2316				
1490691	UM-IC20/DO/16R/1CO/DRY/1500/CS				
1509677	UM-IC20/SC/DO/16R/1CO/CS2214				
1509683	UM-IC20/SC/DO/16R/2CO/CS2214				
1645872	UM-IC20/SPT/16/DI/CS2315				
1645902	UM-IC20/SPT/16/DO/CS2315				
1646579	UM-IC20/SPT/4/AI/CS2315				
1646583	UM-IC20/SPT/4AI/2AO/CS2315				
1490765	UM-IC40/DO/32R/1NO/WET/1500/CS				
1463135	UM-IC50/MK3DS/S7-1500/CS2209				
1463134	UM-IC50/MKKDS/S7-1500/CS2209				
1579865	UM-IC50/SC/32R/DO/1CO/1500/CS				
1579862	UM-IC50/SC/AN/S7-1500/CS				
1670093	UM-SPT/PD/12/CS2316				
1646597	UM-SPT/SPT/12/PD/CS2315				
1646746	UM-SPT/SPT/8/PD/CS2315				
1588119	VF-SET/AN/S7-1500/CS2309				
1588120	VF-SET/DI16/S7-1500/CS2309				
1588114	VF-SET/DO16R/S7-1500/CS2309				
1588389	VF-SET/DO16R/WET/S71500/CS2309				
1588117	VF-SET/DO32R/S7-1500/CS2309				
5100044	UM 72-R- 24DC/ 1				
2903294	RIF-3-RPT-LDP-24DC/3X21				
2903292	RIF-3-RPT-LV-230AC/3X21				
2903293	RIF-3-RPT-LV-120AC/3X21				
2900938	RIF-3-BPT/3X21				
2866051	EMD-SL-3V-400			1336412	MACX-MR-3V-690-PT
2885278	EMD-SL-3V-400-N			1336412	MACX-MR-3V-690-PT
2866077	EMD-SL-PH-400			1336408	MACX-MR-PH-690-PT

Item no.	Item Type	Hardware / Firmware old	Hardware / Firmware new	Item no.	Substitute item Type
2866035	EMD-SL-V-UV-300			1336507	MACX-MR-V-600-PT
2866019	EMD-SL-C-OC-10			1336512	MACX-MR-C-10-PT
2867937	EMD-SL-C-UC-10			1336512	MACX-MR-C-10-PT
2866093	EMD-SL-PTC			1336527	MACX-MR-PTC-PT
2885906	EMD-SL-LL-230				
2885249	EMD-FL-3V-690			1336547	MACX-MR-3V-900-PT
2867979	EMD-FL-3V-500			1336412	MACX-MR-3V-690-PT
2885809	EMD-FL-PF-400				
2866129	EMD-SL-PS-230AC				
2885731	EMD-SL-PS-120AC				
2866116	EMD-SL-PS-110AC				
2866103	EMD-SL-PS- 24AC				
2885294	EMD-SL-PS45-230AC				
2885304	EMD-SL-PS45-400AC				

Item no.;	Type;	old;	new;	Substitute item;	Replacement product designation;	eCl@ss 13.0;
2903139;	CABLE-DB37F-2IC14/0					4/CS1112;;;;;27242220;
1037026;	CABLE-DB37F-OE/S/200/CS1736;;;;;					
1486499;	CABLE-IC20/OE/0					5M/1500/CS;;;;;
1486509;	CABLE-IC20/OE/1					5M/1500/CS;;;;;
1486546;	CABLE-IC20/OE/10					0M/1500/CS;;;;;
1486520;	CABLE-IC20/OE/3					0M/1500/CS;;;;;
1486527;	CABLE-IC20/OE/4					0M/1500/CS;;;;;
1486543;	CABLE-IC20/OE/6					0M/1500/CS;;;;;
1486544;	CABLE-IC20/OE/8					0M/1500/CS;;;;;
1381499;	CABLE-IC34/FE/15					0M/VSF;;;;;
1486563;	CABLE-IC40/OE/0					5M/1500/CS;;;;;
1486565;	CABLE-IC40/OE/1					0M/1500/CS;;;;;
1486877;	CABLE-IC40/OE/10					0M/1500/CS;;;;;
1486599;	CABLE-IC40/OE/3					0M/1500/CS;;;;;
1486604;	CABLE-IC40/OE/4					0M/1500/CS;;;;;
1486873;	CABLE-IC40/OE/6					0M/1500/CS;;;;;
1486876;	CABLE-IC40/OE/8					0M/1500/CS;;;;;
1579870;	CABLE-IC50/IC50/2					5M/1500/CS;;;;;
1646754;	CABLE-VIP20/OE/AIO/1					2M/CS2315;;;;;
1646750;	CABLE-VIP20/OE/DIO/1					2M/CS2315;;;;;
2906139;	CABLE-VIP50-2IC20/15					0M/CS1445;;;;;27242220;
2900169;	FLKM-2FLK40/PMT/SI/Z/YCS;;;;;27141152;					
5775269;	FUSE TR5 SPARE PACKAGE;;;;;27142002;					
1434265;	UM-20DIO/SPT/PT/ZF/CS2025;;;;;					
1579866;	UM-2IC14/SC/16R/DO/1CO/1500/CS;;;;;					
1490672;	UM-2IC14/SC/DI/16/F/1500/CS;;;;;					
1098079;	UM-2MK40/20R/NO/NC/ETSP/CS1831;;;;;					
5774548;	UM72-R-24DC/21HC;;;;;27141152;					
1427419;	UM-DB25M/16R/DI/AC/CS2204;;;;;					

1427429;UM-DB25M/16R/DI/CS2204;;;;;
2909841;UM-DB37F/15R/CO/DO/CS1657;;;;;27141152;
1567896;UM-DB37F/32R/DI/CS2307;;;;;
1567890;UM-DB37F/32R/DO/CS2307;;;;;
1568063;UM-DB37F/AI/CS2307;;;;;
1568058;UM-DB37F/DI/CS2307;;;;;
1568057;UM-DB37F/GT/CS2307;;;;;
2901567;UM-DB37M/16R/DO/CO/J/C300;;;;;27141152;
1551630;UM-DB37M/DI/32R/F/CS2305;;;;;
2908884;UM-EC56F/16/AO/DO/F/CS1633;;;;;
2908879;UM-EC56F/16R/CO/DO/F/CS1629;;;;;
1587634;UM-FLK20/M/16R/DI/F/CS2303;;;;;
1509671;UM-IC10/SC/DO/8R/1CO/CS2214;;;;;
1509674;UM-IC10/SC/DO/8R/2CO/CS2214;;;;;
1670079;UM-IC14/8R/DO/NO/220V/CS2316;;;;;
1670069;UM-IC14/8R/DO/NO/24V/CS2316;;;;;
1670000;UM-IC14/AI/4/CS2316;;;;;
1670050;UM-IC14/DI/8/CS2316;;;;;
1368094;UM-IC14/SC/DO/8R/1CO/DRY/1500;;;;;
1670018;UM-IC20/AO/4/CS2316;;;;;
1490691;UM-IC20/DO/16R/1CO/DRY/1500/CS;;;;;
1509677;UM-IC20/SC/DO/16R/1CO/CS2214;;;;;
1509683;UM-IC20/SC/DO/16R/2CO/CS2214;;;;;
1645872;UM-IC20/SPT/16/DI/CS2315;;;;;
1645902;UM-IC20/SPT/16/DO/CS2315;;;;;
1646579;UM-IC20/SPT/4/AI/CS2315;;;;;
1646583;UM-IC20/SPT/4AI/2AO/CS2315;;;;;
1490765;UM-IC40/DO/32R/1NO/WET/1500/CS;;;;;
1463135;UM-IC50/MK3DS/S7-1500/CS2209;;;;;
1463134;UM-IC50/MKKDS/S7-1500/CS2209;;;;;

1579865;UM-IC50/SC/32R/DO/1CO/1500/CS;;;;;
1579862;UM-IC50/SC/AN/S7-1500/CS;;;;;
1670093;UM-SPT/PD/12/CS2316;;;;;
1646597;UM-SPT/SPT/12/PD/CS2315;;;;;
1646746;UM-SPT/SPT/8/PD/CS2315;;;;;
1588119;VF-SET/AN/S7-1500/CS2309;;;;;
1588120;VF-SET/DI16/S7-1500/CS2309;;;;;
1588114;VF-SET/DO16R/S7-1500/CS2309;;;;;
1588389;VF-SET/DO16R/WET/S71500/CS2309;;;;;
1588117;VF-SET/DO32R/S7-1500/CS2309;;;;;
5100044;UM 72-R- 24DC/ 1;;;;;27371601;
2903294;RIF-3-RPT-LDP-24DC/3X21;;;;;27371601;
2903292;RIF-3-RPT-LV-230AC/3X21;;;;;27371601;
2903293;RIF-3-RPT-LV-120AC/3X21;;;;;27371601;
2900938;RIF-3-BPT/3X21;;;;;27371603;
2866051;EMD-SL-3V-400;;;1336412;MACX-MR-3V-690-PT;27371801;
2885278;EMD-SL-3V-400-N;;;1336412;MACX-MR-3V-690-PT;27371801;
2866077;EMD-SL-PH-400;;;1336408;MACX-MR-PH-690-PT;27371803;
2866035;EMD-SL-V-UV-300;;;1336507;MACX-MR-V-600-PT;27371801;
2866019;EMD-SL-C-OC-10;;;1336512;MACX-MR-C-10-PT;27371802;
2867937;EMD-SL-C-UC-10;;;1336512;MACX-MR-C-10-PT;27371802;
2866093;EMD-SL-PTC;;;1336527;MACX-MR-PTC-PT;27371810;
2885906;EMD-SL-LL-230;;;;;27371813;
2885249;EMD-FL-3V-690;;;1336547;MACX-MR-3V-900-PT;27371801;
2867979;EMD-FL-3V-500;;;1336412;MACX-MR-3V-690-PT;27371801;
2885809;EMD-FL-PF-400;;;;;27371016;
2866129;EMD-SL-PS-230AC;;;;;27371392;
2885731;EMD-SL-PS-120AC;;;;;27371392;
2866116;EMD-SL-PS-110AC;;;;;27371392;
2866103;EMD-SL-PS- 24AC;;;;;27371392;

2885294;EMD-SL-PS45-230AC;;;;;27371392;
2885304;EMD-SL-PS45-400AC;;;;;27371392;

PCN/PDN Number	Customer Number	Company Name	Street	Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)	Phoenix Contact Item Designation (changed/discontinued article)	Report Date	Substitute Item	Replacement Product Designation
IDK250010	401641	TTI, INC.	2441 NORTHEAST PKWY	76106	FORT WORTH	2903294	RIF-3-RPT-LDP-24DC/3X21	13.11.2025		
IDK250010	401641	TTI, INC.	2441 NORTHEAST PKWY	76106	FORT WORTH	2866019	EMD-SL-C-OC-10	13.11.2025	1336512	MACX-MR-C-10-PT
IDK250010	401641	TTI, INC.	2441 NORTHEAST PKWY	76106	FORT WORTH	2885731	EMD-SL-PS-120AC	13.11.2025		
IDK250010	401641	TTI, INC.	2441 NORTHEAST PKWY	76106	FORT WORTH	2866093	EMD-SL-PTC	13.11.2025	1336527	MACX-MR-PTC-PT