

## Product change notification (PCN)

<b>Title / short description</b>	New side label for VAL-SEC
<b>Affected article category</b>	Surge protection and interference filters
<b>Change category</b>	Marking, Characteristics, Documentation
<b>Change number</b>	CCL240020-00
<b>Reason for PCN/PDN Revision</b>	

### Purpose/objective of the change

The side label has been changed to printing

### Detailed description of the change

Addition of the DEKRA on the now printed label

### Identifying characteristics

Identified on the printing

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	-
<b>Effective date (EOP)</b>	2026-05-18	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	-		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier                  | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input checked="" type="checkbox"/> Product improvement with customer benefits |  |
| <input checked="" type="checkbox"/> Others          |  |  |

We will implement this change at short notice so that the benefits of this change can be realized immediately.

### Attachments

- Printing old-new.pdf
- Material\_list.csv
- PCN-CCL240020-00\_EN

## Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1033786	VAL-SEC-T2-2+F-48DC-FM	04	05	-	-
1033788	VAL-SEC-T2-2+F-120DC-FM	04	05	-	-
1033789	VAL-SEC-T2-2+F-220DC-FM	03	04	-	-
1033790	VAL-SEC-T2-2+F-380DC-FM	03	04	-	-
1052632	VAL-SEC-T2-GDT-400DC-P	01	02	-	-
1052649	VAL-SEC-T2-GDT-800DC-P	01	02	-	-
1076468	VAL-SEC-T2-4+0-440-FM	02	03	-	-
2800557	VAL-SE-CP-1S-350/40	08	09	-	-
2800558	VAL-SE-CP-1S-350/20	08	09	-	-
2800559	VAL-SE-CP-1S-350/8	08	09	-	-
2800560	VAL-SE-CP-3C-350/40	08	09	-	-
2800561	VAL-SE-CP-3C-350/20	08	09	-	-
2800562	VAL-SE-CP-3C-350/8	08	09	-	-
2800563	VAL-SE-CP-3S-350/40	08	09	-	-
2800564	VAL-SE-CP-3S-350/20	08	09	-	-
2800565	VAL-SE-CP-3S-350/8	08	09	-	-
2800566	VAL-SE-CP-350/40-ST	08	09	-	-
2800568	VAL-SE-CP-350/20-ST	08	09	-	-
2800569	VAL-SE-CP-350/8-ST	08	09	-	-
2800590	VAL-SE-CP-N/PE/40-ST	09	10	-	-
2905333	VAL-SEC-T2-1S-350-FM	06	07	-	-
2905337	VAL-SEC-T2-2C-350-FM	05	06	-	-
2905338	VAL-SEC-T2-2S-350-FM	05	06	-	-
2905339	VAL-SEC-T2-3C-350-FM	05	06	-	-
2905340	VAL-SEC-T2-3S-350-FM	06	07	-	-
2905341	VAL-SEC-T2-1S-350	05	06	-	-
2905342	VAL-SEC-T2-2C-350	05	06	-	-
2905343	VAL-SEC-T2-2S-350	05	06	-	-
2905344	VAL-SEC-T2-3C-350	04	05	-	-
2905345	VAL-SEC-T2-3S-350	04	05	-	-
2905346	VAL-SEC-T2-350-P	06	07	-	-
2905348	VAL-SEC-T2-1S-175-FM	04	05	-	-
2905350	VAL-SEC-T2-2C-175-FM	04	05	-	-
2905351	VAL-SEC-T2-2S-175-FM	04	05	-	-
2905353	VAL-SEC-T2-3C-175-FM	04	05	-	-
2905354	VAL-SEC-T2-3S-175-FM	05	06	-	-
2905355	VAL-SEC-T2-175-P	03	04	-	-
2905356	VAL-SEC-T2-N/PE-175-P	03	04	-	-

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2907865	VAL-SEC-T2-2+0-48DC-FM	03	04	-	-
2907874	VAL-SEC-T2-2+0-120DC-FM	04	05	-	-
2907875	VAL-SEC-T2-2+0-220DC-FM	03	04	-	-
2907876	VAL-SEC-T2-2+0-380DC-FM	02	03	-	-
2907877	VAL-SEC-T2-48DC-P	04	05	-	-
2907878	VAL-SEC-T2-120DC-P	05	06	-	-
2907879	VAL-SEC-T2-220DC-P	03	04	-	-
2907880	VAL-SEC-T2-380DC-P	02	03	-	-
2909590	VAL-SEC-T2-3S-350VF-FM	03	04	-	-
2909591	VAL-SEC-T2-3C-350VF-FM	02	03	-	-
2909592	VAL-SEC-T2-1S-350VF-FM	02	03	-	-
2909596	VAL-SEC-T2-350VF-P	01	02	-	-
2909635	VAL-SEC-T2-3S-350/40-FM	03	04	-	-
2909636	VAL-SEC-T2-N/PE-264/40-P	01	02	-	-
2909637	VAL-SEC-T2-3S-350/40	02	03	-	-
2909968	VAL-SEC-T2-3C-440-FM	03	04	-	-
2909969	VAL-SEC-T2-440-P	01	02	-	-



Phoenix Contact Art.Nr.;	Phoenix Contact Art.Bez.;	Bemerkung
1033786	;VAL-SEC-T2-2+F-48DC-FM;HW/FW alt: 4	HW/FW neu: 5
1033788	;VAL-SEC-T2-2+F-120DC-FM;HW/FW alt: 4	HW/FW neu: 5
1033789	;VAL-SEC-T2-2+F-220DC-FM;HW/FW alt: 3	HW/FW neu: 4
1033790	;VAL-SEC-T2-2+F-380DC-FM;HW/FW alt: 3	HW/FW neu: 4
1052632	;VAL-SEC-T2-GDT-400DC-P;HW/FW alt: 1	HW/FW neu: 2
1052649	;VAL-SEC-T2-GDT-800DC-P;HW/FW alt: 1	HW/FW neu: 2
1076468	;VAL-SEC-T2-4+0-440-FM;HW/FW alt: 2	HW/FW neu: 3
2800557	;VAL-SE-CP-1S-350/40;HW/FW alt: 8	HW/FW neu: 9
2800558	;VAL-SE-CP-1S-350/20;HW/FW alt: 8	HW/FW neu: 9
2800559	;VAL-SE-CP-1S-350/8;HW/FW alt: 8	HW/FW neu: 9
2800560	;VAL-SE-CP-3C-350/40;HW/FW alt: 8	HW/FW neu: 9
2800561	;VAL-SE-CP-3C-350/20;HW/FW alt: 8	HW/FW neu: 9
2800562	;VAL-SE-CP-3C-350/8;HW/FW alt: 8	HW/FW neu: 9
2800563	;VAL-SE-CP-3S-350/40;HW/FW alt: 8	HW/FW neu: 9
2800564	;VAL-SE-CP-3S-350/20;HW/FW alt: 8	HW/FW neu: 9
2800565	;VAL-SE-CP-3S-350/8;HW/FW alt: 8	HW/FW neu: 9
2800566	;VAL-SE-CP-350/40-ST;HW/FW alt: 8	HW/FW neu: 9
2800568	;VAL-SE-CP-350/20-ST;HW/FW alt: 8	HW/FW neu: 9
2800569	;VAL-SE-CP-350/8-ST;HW/FW alt: 8	HW/FW neu: 9
2800590	;VAL-SE-CP-N/PE/40-ST;HW/FW alt: 9	HW/FW neu: 10
2905333	;VAL-SEC-T2-1S-350-FM;HW/FW alt: 6	HW/FW neu: 7
2905337	;VAL-SEC-T2-2C-350-FM;HW/FW alt: 5	HW/FW neu: 6
2905338	;VAL-SEC-T2-2S-350-FM;HW/FW alt: 5	HW/FW neu: 6
2905339	;VAL-SEC-T2-3C-350-FM;HW/FW alt: 5	HW/FW neu: 6
2905340	;VAL-SEC-T2-3S-350-FM;HW/FW alt: 6	HW/FW neu: 7
2905341	;VAL-SEC-T2-1S-350;HW/FW alt: 5	HW/FW neu: 6
2905342	;VAL-SEC-T2-2C-350;HW/FW alt: 5	HW/FW neu: 6
2905343	;VAL-SEC-T2-2S-350;HW/FW alt: 5	HW/FW neu: 6
2905344	;VAL-SEC-T2-3C-350;HW/FW alt: 4	HW/FW neu: 5
2905345	;VAL-SEC-T2-3S-350;HW/FW alt: 4	HW/FW neu: 5
2905346	;VAL-SEC-T2-350-P;HW/FW alt: 6	HW/FW neu: 7
2905348	;VAL-SEC-T2-1S-175-FM;HW/FW alt: 4	HW/FW neu: 5
2905350	;VAL-SEC-T2-2C-175-FM;HW/FW alt: 4	HW/FW neu: 5
2905351	;VAL-SEC-T2-2S-175-FM;HW/FW alt: 4	HW/FW neu: 5
2905353	;VAL-SEC-T2-3C-175-FM;HW/FW alt: 4	HW/FW neu: 5
2905354	;VAL-SEC-T2-3S-175-FM;HW/FW alt: 5	HW/FW neu: 6
2905355	;VAL-SEC-T2-175-P;HW/FW alt: 3	HW/FW neu: 4
2905356	;VAL-SEC-T2-N/PE-175-P;HW/FW alt: 3	HW/FW neu: 4
2907865	;VAL-SEC-T2-2+0-48DC-FM;HW/FW alt: 3	HW/FW neu: 4
2907874	;VAL-SEC-T2-2+0-120DC-FM;HW/FW alt: 4	HW/FW neu: 5
2907875	;VAL-SEC-T2-2+0-220DC-FM;HW/FW alt: 3	HW/FW neu: 4
2907876	;VAL-SEC-T2-2+0-380DC-FM;HW/FW alt: 2	HW/FW neu: 3
2907877	;VAL-SEC-T2-48DC-P;HW/FW alt: 4	HW/FW neu: 5

2907878	;VAL-SEC-T2-120DC-P;HW/FW alt: 5	HW/FW neu: 6
2907879	;VAL-SEC-T2-220DC-P;HW/FW alt: 3	HW/FW neu: 4
2907880	;VAL-SEC-T2-380DC-P;HW/FW alt: 2	HW/FW neu: 3
2909590	;VAL-SEC-T2-3S-350VF-FM;HW/FW alt: 3	HW/FW neu: 4
2909591	;VAL-SEC-T2-3C-350VF-FM;HW/FW alt: 2	HW/FW neu: 3
2909592	;VAL-SEC-T2-1S-350VF-FM;HW/FW alt: 2	HW/FW neu: 3
2909596	;VAL-SEC-T2-350VF-P;HW/FW alt: 1	HW/FW neu: 2
2909635	;VAL-SEC-T2-3S-350/40-FM;HW/FW alt: 3	HW/FW neu: 4
2909636	;VAL-SEC-T2-N/PE-264/40-P;HW/FW alt: 1	HW/FW neu: 2
2909637	;VAL-SEC-T2-3S-350/40;HW/FW alt: 2	HW/FW neu: 3
2909968	;VAL-SEC-T2-3C-440-FM;HW/FW alt: 3	HW/FW neu: 4
2909969	;VAL-SEC-T2-440-P;HW/FW alt: 1	HW/FW neu: 2

eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27400501  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27400501  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171302  
eCl@ss 11.0: 27171292

eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171292  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171202  
eCl@ss 11.0: 27171292

Kunde;Name 1;Name 2;Name 3;Name 4;Straße;PLZ;Stadt;

Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Ihre Materialnr.;Menge 2024 ST;Menge 2025 ST;Menge 2026 ST;AE :  
Inc.;;;Ganghoferstraße 34;82216;Maisach;2905339 ;VAL-SEC-T2-3C-350-FM;PHX2905339;;;10 ST;10  
49786 ;TTI

2026 ST  
J ST

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1033786;VAL-SEC-T2-2+F-48DC-FM;04;05;-;-;27171302;  
1033788;VAL-SEC-T2-2+F-120DC-FM;04;05;-;-;27171302;  
1033789;VAL-SEC-T2-2+F-220DC-FM;03;04;-;-;27171302;  
1033790;VAL-SEC-T2-2+F-380DC-FM;03;04;-;-;27171302;  
1052632;VAL-SEC-T2-GDT-400DC-P;01;02;-;-;27171292;  
1052649;VAL-SEC-T2-GDT-800DC-P;01;02;-;-;27171292;  
1076468;VAL-SEC-T2-4+0-440-FM;02;03;-;-;27171202;  
2800557;VAL-SE-CP-1S-350/40;08;09;-;-;27171202;  
2800558;VAL-SE-CP-1S-350/20;08;09;-;-;27171202;  
2800559;VAL-SE-CP-1S-350/8;08;09;-;-;27171202;  
2800560;VAL-SE-CP-3C-350/40;08;09;-;-;27171202;  
2800561;VAL-SE-CP-3C-350/20;08;09;-;-;27171202;  
2800562;VAL-SE-CP-3C-350/8;08;09;-;-;27171202;  
2800563;VAL-SE-CP-3S-350/40;08;09;-;-;27171202;  
2800564;VAL-SE-CP-3S-350/20;08;09;-;-;27171202;  
2800565;VAL-SE-CP-3S-350/8;08;09;-;-;27171202;  
2800566;VAL-SE-CP-350/40-ST;08;09;-;-;27400501;  
2800568;VAL-SE-CP-350/20-ST;08;09;-;-;27171292;  
2800569;VAL-SE-CP-350/8-ST;08;09;-;-;27400501;  
2800590;VAL-SE-CP-N/PE/40-ST;09;10;-;-;27171292;  
2905333;VAL-SEC-T2-1S-350-FM;06;07;-;-;27171202;  
2905337;VAL-SEC-T2-2C-350-FM;05;06;-;-;27171202;  
2905338;VAL-SEC-T2-2S-350-FM;05;06;-;-;27171202;  
2905339;VAL-SEC-T2-3C-350-FM;05;06;-;-;27171202;  
2905340;VAL-SEC-T2-3S-350-FM;06;07;-;-;27171202;  
2905341;VAL-SEC-T2-1S-350;05;06;-;-;27171202;  
2905342;VAL-SEC-T2-2C-350;05;06;-;-;27171202;  
2905343;VAL-SEC-T2-2S-350;05;06;-;-;27171202;  
2905344;VAL-SEC-T2-3C-350;04;05;-;-;27171202;  
2905345;VAL-SEC-T2-3S-350;04;05;-;-;27171202;  
2905346;VAL-SEC-T2-350-P;06;07;-;-;27171292;  
2905348;VAL-SEC-T2-1S-175-FM;04;05;-;-;27171202;  
2905350;VAL-SEC-T2-2C-175-FM;04;05;-;-;27171202;  
2905351;VAL-SEC-T2-2S-175-FM;04;05;-;-;27171202;  
2905353;VAL-SEC-T2-3C-175-FM;04;05;-;-;27171202;  
2905354;VAL-SEC-T2-3S-175-FM;05;06;-;-;27171202;  
2905355;VAL-SEC-T2-175-P;03;04;-;-;27171292;  
2905356;VAL-SEC-T2-N/PE-175-P;03;04;-;-;27171292;  
2907865;VAL-SEC-T2-2+0-48DC-FM;03;04;-;-;27171302;  
2907874;VAL-SEC-T2-2+0-120DC-FM;04;05;-;-;27171302;  
2907875;VAL-SEC-T2-2+0-220DC-FM;03;04;-;-;27171302;  
2907876;VAL-SEC-T2-2+0-380DC-FM;02;03;-;-;27171302;  
2907877;VAL-SEC-T2-48DC-P;04;05;-;-;27171292;

2907878;VAL-SEC-T2-120DC-P;05;06;-;-;27171292;  
2907879;VAL-SEC-T2-220DC-P;03;04;-;-;27171292;  
2907880;VAL-SEC-T2-380DC-P;02;03;-;-;27171292;  
2909590;VAL-SEC-T2-3S-350VF-FM;03;04;-;-;27171202;  
2909591;VAL-SEC-T2-3C-350VF-FM;02;03;-;-;27171202;  
2909592;VAL-SEC-T2-1S-350VF-FM;02;03;-;-;27171202;  
2909596;VAL-SEC-T2-350VF-P;01;02;-;-;27171292;  
2909635;VAL-SEC-T2-3S-350/40-FM;03;04;-;-;27171202;  
2909636;VAL-SEC-T2-N/PE-264/40-P;01;02;-;-;27171292;  
2909637;VAL-SEC-T2-3S-350/40;02;03;-;-;27171202;  
2909968;VAL-SEC-T2-3C-440-FM;03;04;-;-;27171202;  
2909969;VAL-SEC-T2-440-P;01;02;-;-;27171292;