

Product change notification (PCN)

Title / short description	PTCB TM - Approval change
Affected article category	Protective devices
Change category	Approval, Marking
Change number	CCL260042-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

DNV certification for PTCB TM1/TM2 and CCC compliance for PTCB TM1.

Detailed description of the change

The PTCB TM1 and PTCB TM2 product families obtain DNV approval. In addition, CCC compliance has been confirmed for the PTCB TM1 product family. The product labeling will be updated accordingly.

Identifying characteristics

Increase of the production batch (V/C)

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-08-31	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PCN-CCL260042-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1509512	PTCB TM1 0.5A F2 NO P	00	01		
1509519	PTCB TM1 1A F2 NO P	00	01		
1509520	PTCB TM1 2A F2 NO P	00	01		
1509522	PTCB TM1 3A F2 NO P	00	01		
1509524	PTCB TM1 4A F2 NO P	00	01		
1509528	PTCB TM1 5A F2 NO P	00	01		
1509529	PTCB TM1 6A F2 NO P	00	01		
1509532	PTCB TM1 8A F2 NO P	00	01		
1509535	PTCB TM1 10A F2 NO P	00	01		
1509537	PTCB TM1 12A F2 NO P	00	01		
1567580	PTCB TM1 16A F2 NO P	00	01		
1575555	PTCB TM1 0.5A M1 NO P	00	01		
1575557	PTCB TM1 1A M1 NO P	00	01		
1575558	PTCB TM1 2A M1 NO P	00	01		
1575565	PTCB TM1 3A M1 NO P	00	01		
1575566	PTCB TM1 4A M1 NO P	00	01		
1575571	PTCB TM1 5A M1 NO P	00	01		
1575572	PTCB TM1 6A M1 NO P	00	01		
1575573	PTCB TM1 8A M1 NO P	00	01		
1575580	PTCB TM1 10A M1 NO P	00	01		
1575581	PTCB TM1 12A M1 NO P	00	01		
1575586	PTCB TM1 16A M1 NO P	00	01		
1575587	PTCB TM2 0.5A F2 NO P	00	01		
1575588	PTCB TM2 1A F2 NO P	00	01		
1575590	PTCB TM2 2A F2 NO P	00	01		
1575591	PTCB TM2 3A F2 NO P	00	01		
1575593	PTCB TM2 4A F2 NO P	00	01		
1575595	PTCB TM2 5A F2 NO P	00	01		
1575597	PTCB TM2 6A F2 NO P	00	01		
1575598	PTCB TM2 8A F2 NO P	00	01		
1575599	PTCB TM2 10A F2 NO P	00	01		
1575613	PTCB TM2 12A F2 NO P	00	01		
1575616	PTCB TM2 16A F2 NO P	00	01		
1575617	PTCB TM2 0.5A M1 NO P	00	01		
1575618	PTCB TM2 1A M1 NO P	00	01		
1575619	PTCB TM2 2A M1 NO P	00	01		
1575621	PTCB TM2 3A M1 NO P	00	01		
1575622	PTCB TM2 4A M1 NO P	00	01		

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1575623	PTCB TM2 5A M1 NO P	00	01		
1575624	PTCB TM2 6A M1 NO P	00	01		
1575625	PTCB TM2 8A M1 NO P	00	01		
1575626	PTCB TM2 10A M1 NO P	00	01		
1575629	PTCB TM2 12A M1 NO P	00	01		
1575632	PTCB TM2 16A M1 NO P	00	01		
1567576	PTCB BE PT 6	00	01		
1760600	PTCB BE PT 6/10	00	01		

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1509512;PTCB TM1 0.5A F2 NO P;00;01;;;27140401;
1509519;PTCB TM1 1A F2 NO P;00;01;;;27140401;
1509520;PTCB TM1 2A F2 NO P;00;01;;;27140401;
1509522;PTCB TM1 3A F2 NO P;00;01;;;27140401;
1509524;PTCB TM1 4A F2 NO P;00;01;;;27140401;
1509528;PTCB TM1 5A F2 NO P;00;01;;;27140401;
1509529;PTCB TM1 6A F2 NO P;00;01;;;27140401;
1509532;PTCB TM1 8A F2 NO P;00;01;;;27140401;
1509535;PTCB TM1 10A F2 NO P;00;01;;;27140401;
1509537;PTCB TM1 12A F2 NO P;00;01;;;27140401;
1567580;PTCB TM1 16A F2 NO P;00;01;;;27140401;
1575555;PTCB TM1 0.5A M1 NO P;00;01;;;27140401;
1575557;PTCB TM1 1A M1 NO P;00;01;;;27140401;
1575558;PTCB TM1 2A M1 NO P;00;01;;;27140401;
1575565;PTCB TM1 3A M1 NO P;00;01;;;27140401;
1575566;PTCB TM1 4A M1 NO P;00;01;;;27140401;
1575571;PTCB TM1 5A M1 NO P;00;01;;;27140401;
1575572;PTCB TM1 6A M1 NO P;00;01;;;27140401;
1575573;PTCB TM1 8A M1 NO P;00;01;;;27140401;
1575580;PTCB TM1 10A M1 NO P;00;01;;;27140401;
1575581;PTCB TM1 12A M1 NO P;00;01;;;27140401;
1575586;PTCB TM1 16A M1 NO P;00;01;;;27140401;
1575587;PTCB TM2 0.5A F2 NO P;00;01;;;27140401;
1575588;PTCB TM2 1A F2 NO P;00;01;;;27140401;
1575590;PTCB TM2 2A F2 NO P;00;01;;;27140401;
1575591;PTCB TM2 3A F2 NO P;00;01;;;27140401;
1575593;PTCB TM2 4A F2 NO P;00;01;;;27140401;
1575595;PTCB TM2 5A F2 NO P;00;01;;;27140401;
1575597;PTCB TM2 6A F2 NO P;00;01;;;27140401;
1575598;PTCB TM2 8A F2 NO P;00;01;;;27140401;
1575599;PTCB TM2 10A F2 NO P;00;01;;;27140401;
1575613;PTCB TM2 12A F2 NO P;00;01;;;27140401;
1575616;PTCB TM2 16A F2 NO P;00;01;;;27140401;
1575617;PTCB TM2 0.5A M1 NO P;00;01;;;27140401;
1575618;PTCB TM2 1A M1 NO P;00;01;;;27140401;
1575619;PTCB TM2 2A M1 NO P;00;01;;;27140401;
1575621;PTCB TM2 3A M1 NO P;00;01;;;27140401;
1575622;PTCB TM2 4A M1 NO P;00;01;;;27140401;
1575623;PTCB TM2 5A M1 NO P;00;01;;;27140401;
1575624;PTCB TM2 6A M1 NO P;00;01;;;27140401;
1575625;PTCB TM2 8A M1 NO P;00;01;;;27140401;
1575626;PTCB TM2 10A M1 NO P;00;01;;;27140401;
1575629;PTCB TM2 12A M1 NO P;00;01;;;27140401;
1575632;PTCB TM2 16A M1 NO P;00;01;;;27140401;
1567576;PTCB BE PT 6;00;01;;;27140401;
1760600;PTCB BE PT 6/10;00;01;;;27140401;

PCN/PDN Number	Customer Number	Company Name	Street
CCL260042	401641	TTI, INC.	2441 NORTHEAST PKWY
CCL260042	401641	TTI, INC.	2441 NORTHEAST PKWY
CCL260042	401641	TTI, INC.	2441 NORTHEAST PKWY
CCL260042	401641	TTI, INC.	2441 NORTHEAST PKWY
CCL260042	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	1509512
76106	FORT WORTH	1575572
76106	FORT WORTH	1567576
76106	FORT WORTH	1575565
76106	FORT WORTH	1575558

Phoenix Contact Item Designation (changed/discontinued article)	Report Date	Substitute Item
PTCB TM1 0.5A F2 NO P	31.08.2026	
PTCB TM1 6A M1 NO P	31.08.2026	
PTCB BE PT 6	31.08.2026	
PTCB TM1 3A M1 NO P	31.08.2026	
PTCB TM1 2A M1 NO P	31.08.2026	

Replacement Product Designation