

Product discontinuation notification (PDN)

Title / short description	Portfolio streamlining data connectors and cables
Affected article category	Connector
Change category	Discontinuation
Change number	IAF260004-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation of items

Detailed description of the change

Due to the market development and the resulting decline in demand, the listed items are no longer commercially viable for Phoenix Contact. For this reason, production and sales will be discontinued as of the effective date stated in this notice.

Recommended replacement items are listed below.

If you need information about remaining delivery quantities, last-time-buy options, or further commercial details, please contact your local Sales organization.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-04-30
Effective date (EOP)	2027-04-30	End of Service (EOSR)	-
End of Sales (EOS)	2026-10-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IAF260004-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1414106	FOC-SC-LC-OM4-LS-CABLE/3			1115599	FOC-LC:PA-SC:PA-OM4:D01/3
1414107	FOC-SC-LC-OS2-LS-CABLE/3			1115616	FOC-LC:PA-SC:PA-OS2:D01/3
1145397	FOC-FDX20-FR19-STD24-OM2-PT9			1145407	FOC-FDX20-FR19-SCD24-OM2-PT9
1145416	FOC-FDX20-FR19-LCD12-OM2-PT9			1145408	FOC-FDX20-FR19-SCD12-OM2-PT9
1187028	SPE-STRM-90 W01			1163797	SPE-T1-STRM-90
1292763	SPE-STRM-90-LED W01			1215778	SPE-T1-STRM-90-LED
2700301	FL CAT5 PATCH 0,24			1227558	NBC-R4OC/0,3-BC5/R4OC
1422639	NBC-R4AC/45,0-93E/R4AC			1247639	NBC-R4ACS-R4ACS-IE8/.../...
1422790	NBC-R4AC/0,13-94B/R4AC			1247639	NBC-R4ACS-R4ACS-IE8/.../...
1422833	NBC-R4AC/1,75-94B/R4AC			1247639	NBC-R4ACS-R4ACS-IE8/.../...
1410447	CUC-V14-P2PBK H01			1405329	VS-PPC-F2-PC-POBK
1414100	FOC-TOOL-STRIPPING-FA-2			1407016	FOC-TOOL-STRIPPING-T-1
1407754	VS-IP67/B-OE-94B-LI/5,0			1407725	VS-IP67-OE-94B-LI/5,0
1408028	FOC-V14-C1ZNI-T/SJFP			1407896	FOC-V14-C1ZNI-S/SJFP
1407902	FOC-V14-C1ZNI-B/SJFP			1407896	FOC-V14-C1ZNI-S/SJFP
1404197	VS-PPC-C1-SCRJ-POBK-PG9-A4D-SI			1407896	FOC-V14-C1ZNI-S/SJFP
1407961	VS-IP67/B-IP20-94B-LI/5,0			1407932	VS-IP67-IP20-94B-LI/5,0
1408956	NBC-R4MC/2,0-94B/R4MC			1411846	NBC-R4MC-R4MC-IE8/.../...
1408955	NBC-R4MC/1,0-94B/R4MC			1411846	NBC-R4MC-R4MC-IE8/.../...
1416138	VS-PPC/ME-IP20-93B-LI/5,0			1411863	NBC-R4AC-R4RC-PN4/.../...
1416141	VS-PPC/PL-IP20-93B-LI/5,0			1411864	NBC-R4AC-R4QC-PN4/.../...
1408978	NBC-R4QC/1,0-93B/R4QC			1411867	NBC-R4QC-R4QC-PN4/.../...
1408980	NBC-R4QC/10,0-93B/R4QC			1411867	NBC-R4QC-R4QC-PN4/.../...
1408979	NBC-R4QC/2,0-93B/R4QC			1411867	NBC-R4QC-R4QC-PN4/.../...
1405235	VS-PPC-F1-SCRJ-MNNA-1C-F			1413964	FOC-V14-F1ZNI-EM/SJB
1422663	CUC-V14-C1ZNI-T/R4E8			1422661	CUC-V14-C1ZNI-S/R4E8
1422662	CUC-V14-C1ZNI-B/R4E8			1422661	CUC-V14-C1ZNI-S/R4E8
1422677	CUC-V14-C1ZNI-B/R4E8:10			1422661	CUC-V14-C1ZNI-S/R4E8
1422667	CUC-V14-C1ZNI-T/R4P8			1422664	CUC-V14-C1ZNI-S/R4P8
1422672	CUC-V14-C1ZNI-B/R4P8:10			1422665	CUC-V14-C1ZNI-B/R4P8
1032275	CUC-PPC-C2ZNI-SX/24FKP5:FCWO			1425514	CUC-PPC-C2ZNI-SX/24FKP5:FC
1404210	VS-PPC-C1-SCRJ-POBK-PG9-A3C-SI			1608045	VS-PPC-C1-SCRJ-MNNA-PG9-A3C-C
1404142	VS-PPC-C1-RJ45-POBK-PG9-4Q5-OL			1608126	VS-PPC-C1-RJ45-POBK-PG9-4Q5
1413297	NBC-P2RM/2,0-1020/P2RM B02			1609206	VS-P1220-P1220-C1020/...
1417294	VS-08-RJ45-5-Q/IP67 TIA568A			1656990	VS-08-RJ45-5-Q/IP67
1401301	VS-PP-F-SCRJ LUE			1658121	VS-PP-F-SCRJ
1018526	FOC-17P12-17P12-GL02/10			1792567	FOC-17P12-17P12-GL02/10-T
1018559	FOC-17P12-17P12-GL02/90			1807793	FOC-17P12-17P12-GL02/90-T

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1018557	FOC-17P12-17P12-GL02/80			1807796	FOC-17P12-17P12-GL02/80 -T
1018556	FOC-17P12-17P12-GL02/70			1807797	FOC-17P12-17P12-GL02/70-T
1018494	FOC-17P12-17P12-GL02/5			1807805	FOC-17P12-17P12-GL02/5 -T
1019181	FOC-17P12-17P12-GL02/20			1807810	FOC-17P12-17P12-GL02/20-T
1018560	FOC-17P12-17P12-GL02/100			1807812	FOC-17P12-17P12-GL02/100-T
1018567	FOC-17S12-LCD6-GF02/2			1807815	FOC-17S12-LCD6-GF02/2-T
1018568	FOC-FR19:1U-17S12-LCD6-OM1			1807821	FOC-FR19:1U-17S12-LCD6-OM1-T
1018571	FOC-MODUL:3U-17S12-LCD6-OM1			1807823	FOC-MODUL:3U-17S12-LCD6-OM1-T
1403374	VS-M12FSBP-IP20-94C-LI/1,0				
1412453	NBC-R4RC/0,6-93B/R4RC B02				
1141117	NBC-R4BQ/1,7-937/R4BQ-CO				
1203270	NBC-R4BQ/0,8-937/R4BQ-CO				
1203271	NBC-R4BQ/1,0-937/R4BQ-CO				
1267941	NBC-R4BQ/0,54-937/R4BQ-CO				
1141118	NBC-R4BQ/1,2-937/R4BQ-CO				
1416907	VS-IP20-IP20-94B-LI/91				
1408932	NBC-R4AC/2,0-94B/F4AQ B02				
1408929	NBC-R4AC/1,0-94B/F4AQ B02				
1394242	NBC-R4AC/43,0-94B/R4RC T06				
1394241	NBC-R4AC/33,0-94B/R4RC T06				
1394229	NBC-R4AC/13,0-94B/R4RC T06				
1394239	NBC-R4AC/23,0-94B/R4RC T06				
1657782	RDM-SCRJ-KS-9005				
1657779	RDM-SCRJ-T-IP67-9005-OLOGO				
1573141	VS-PPC-F1-RJ45-MNNA-1R-F-RDM				
1404781	VS-PPC-C1-PC67-POBK SET SI/100				
1032393	CUC-V14-A2RBK-PC:5 S01				
1412347	NBC-P2RM/2,0-1020/OE B02				
1413296	NBC-P2RM/10,0-1020 B02				
1064635	CUC-V14-P1RBK/R4 WG:500 E02				
1064633	CUC-V14-P2RBK/24 WG:500 E02				
1657847	VS-PPC-F1-RJ45-P0BK-1R-PHA				
1416192	VS-PPC/ME-IP20-93C-LI/5,0				
1419175	VS-PPC/PL-OE-93K-LI/5,0				
1416173	VS-BU/PN-IP20-93B-LI/2,0				
1408947	NBC-R4QC/1,0-93E/R4QC				
1408941	NBC-R4RC/1,0-93E/R4RC				
1413492	VS-PPC/ME-PPC/ME-94C-LI/10,0				
1423084	VS-IP20-IP20/LG-94B-LI/2,5				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1412943	VS-PPC/ME-IP20-94C-LI/2,0				
1412736	VS-PPC/ME-OE-94C-LI/2,0				
1412024	VS-PPC/PL-IP20-94B-LI/5,0				
1408963	NBC-R4RC/10,0-94B/R4RC				
1408967	NBC-R4QC/10,0-94B/R4QC				
1415526	VS-IP67/B-IP20-94F-LI/5,0				
1415885	VS-PPC/ME-PPC/ME-94F-LI/5,0				
1415298	VS-IP67-OE-94F-LI/5,0				
2744827	FL CAT5 HEAVY CONF/				
2744843	FL CAT5 FLEX CONF/				
2891327	FL PLUG GUARD KEY				
2891712	FL PLUG GUARD RD				
2891819	FL PLUG GUARD WH				
2891615	FL PLUG GUARD GN				
2891220	FL PORT GUARD				
1688667	VS-08-A-RJ45/LP-4-IP 20				
1689970	VS-25-ST-DSUB-5P				
1655438	VS-25-BU-DSUB-5P-LH				
1689983	VS-25-BU-DSUB-5P				
1415756	NBC-D5DM/1,5-920/D5DF E01				
1415757	NBC-D5DM/2,5-920/D5DM E01				
1654840	VS-09-A-GC-BLANK				
1332073	CUC-HDMI-J1ST-S/HAF-SMD				
1332071	CUC-HDMI-J1ST-AH/HAF-SMD				
1332082	NBC-HDMI-HAM/2,0-PVC/HAM				
1332079	NBC-HDMI-HAM/1,0-PVC/HAM				
1332086	NBC-HDMI-HAM/7,5-PVC/HAM				
1332084	NBC-HDMI-HAM/5,0-PVC/HAM				
1332078	NBC-HDMI-HAM/0,5-PVC/HAM				
1332081	NBC-HDMI-HAM/1,5-PVC/HAM				
1332077	NBC-HDMI-HAM/0,3-PVC/HAM				
1332083	NBC-HDMI-HAM/3,0-PVC/HAM				
1717821	FOC-17P24-17P24-GL03/2.1				
1717823	FOC-17S24-ST:A24-GF03/3.5				
1717824	FOC-17S24-ST:A24-GF03/3X				
1657601	VS-SCRJ-POF-CONF				
1402191	FOC-HCS-RUGGED-1014/...				
1719982	FOC-LC:PA-LC:PA-OS2:D01/80				
1719981	FOC-LC:PA-LC:PA-OS2:D01/15				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1041820	FOC-I-D1PGY-S/MPAGC				
1041840	FOC-I-D1PGY-S/MPBGC				
1407019	FOC-TOOL-CERAMIC-BLADE				
1414104	FOC-TOOL-CLEANINGWIPE				
1414105	FOC-TOOL-MARKER BK				
1414098	FOC-TOOL-LIGHTSOURCE-650				
1406995	FOC-TOOL-DISPENSER				
1334222	FOC-CAGE:SFP/SFP+:1X4:PI				
1041881	NBC-PP-F1PWH:10				
1041860	NBC-PP-P1PGY:10				
1419182	VS-V1-C-RJ45-MNNA-PG9-8-I-5-S				
1419185	VS-V1-F-RJ45-MNNA-1-C-S-JI-S				
1419184	VS-V1-F-RJ45-MNNA-1-C-S-JJ-S				
1419183	VS-V1-C-PC-POBK				
1419186	VS-V1-F-PC-POBK				
1652402	VS-08-A-RJ45/MOD-1-IP67-SETLSA				
1688654	VS-08-A-RJ45/LP-2-IP 20				
1655742	VS-04-2X2X26C7/7-67A/OE/1,0				
1655768	VS-04-2X2X26C7/7-67A/OE/5,0				
1655755	VS-04-2X2X26C7/7-67A/OE/2,0				
1653883	VS-04-2X2X26C7/7-67A/67B/5,0				
1653870	VS-04-2X2X26C7/7-67A/67B/2,0				
1653906	VS-04-2X2X26C7/7-67A/SDB/5,0				
1653919	VS-04-2X2X26C7/7-67B/SDA/2,0				
1653922	VS-04-2X2X26C7/7-67B/SDA/5,0				
1653867	VS-04-BUB-FK-F/IP67				
1653854	VS-04-BUA-FK-F/IP67				
1563193	VS-04-SCHLITTEN-USB				
1464014	CUC-V14-C1ZNI-S/R4IV8				
1657889	VS-PPC-F1-SCRJ-POBK-1RP				
1137044	VS-WASHER-3,2 B04				
1413989	CUC-V14-A1ZNI-S180				
1417858	NBC-M12MS/1,5-971/R4AQ VR				
1412976	NBC-M12FR/3,5-971/R4AQ VR				
1412401	NBC-M12FS/1,5-971/R4AQ VR				
1406247	VS-M12FSBP-IP67-93E-LI/2,0				
1406399	VS-M12FSBP-IP67/B-93E-LI/2,0				
1221641	NBC-M12FSBPS-RJ45S-93B/0,12				
1423350	NBC-FSDBP-PG9/0,5-93E/R4AC				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1418713	NBC-MSDBP/1,0-937/R4AQ				
1413493	NBC-FSDBPS/0,33-93B/R4ACR				
1420603	NBC-FSDBP/0,25-937/R4AQ				
1274876	NBC-R4AC/0,3-93T/DSUB09F S10				
1274882	NBC-DSUB09M/0,2-93T/DSUB09F S10				
1274881	NBC-FS/2,0-93T/DSUB09F S10				
1415041	Q2-MUTTER16-RND-OL-BK R03				
1523566	RDM-08-SD-F VPE500				
1408001	VS-PPC-C1-PC67-MNNA P01				
1413295	NBC-P2RM/5,0-1020 B02				
1404359	VS-MSTBAH 2,5/ 5-GB-5,08-BKA-SI				
1445800	VS-M12FSBP-IP20-94B-LI/5,0 HDM				
1423476	NBC-MSDBP/0,5-93E/R4AC				

Phoenix Contact Art.Nr.;	Phoenix Contact Art.Bez.;	Phoenix Contact Alternativ Art.Nr.;	Phoenix Contact Alternativ Ar
1414106	;FOC-SC-LC-OM4-LS-CABLE/3;1115599		;FOC-LC:PA-SC:PA-OM4:D01/3;3
1414107	;FOC-SC-LC-OS2-LS-CABLE/3;1115616		;FOC-LC:PA-SC:PA-OS2:D01/3;3
1145397	;FOC-FDX20-FR19-STD24-OM2-PT9;1145407		;FOC-FDX20-FR19-SCD24-I
1145416	;FOC-FDX20-FR19-LCD12-OM2-PT9;1145408		;FOC-FDX20-FR19-SCD12-
1187028	;SPE-STRM-90 W01;1163797	;SPE-T1-STRM-90;31.10.2026;30.04.2027;e	
1292763	;SPE-STRM-90-LED W01;1215778	;SPE-T1-STRM-90-LED;31.10.2026;30.04.2027;e	
2700301	;FL CAT5 PATCH 0		
1422639	;NBC-R4AC/45		
1422790	;NBC-R4AC/0		
1422833	;NBC-R4AC/1		
1410447	;CUC-V14-P2PBK H01;1405329	;VS-PPC-F2-PC-POBK;31.10.2026;30.04.2027;e	
1414100	;FOC-TOOL-STRIPPING-FA-2;1407016	;FOC-TOOL-STRIPPING-T-1;31.10.2026;30.04.2027;e	
1407754	;VS-IP67/B-OE-94B-LI/5		
1408028	;FOC-V14-C1ZNI-T/SJFP;1407896	;FOC-V14-C1ZNI-S/SJFP;31.10.2026;30.04.2027;e	
1407902	;FOC-V14-C1ZNI-B/SJFP;1407896	;FOC-V14-C1ZNI-S/SJFP;31.10.2026;30.04.2027;e	
1404197	;VS-PPC-C1-SCRJ-POBK-PG9-A4D-SI;1407896	;FOC-V14-C1ZNI-S/SJFP;31.10.2026;30.04.2027;e	
1407961	;VS-IP67/B-IP20-94B-LI/5		
1408956	;NBC-R4MC/2		
1408955	;NBC-R4MC/1		
1416138	;VS-PPC/ME-IP20-93B-LI/5		
1416141	;VS-PPC/PL-IP20-93B-LI/5		
1408978	;NBC-R4QC/1		
1408980	;NBC-R4QC/10		
1408979	;NBC-R4QC/2		
1405235	;VS-PPC-F1-SCRJ-MNNA-1C-F;1413964	;FOC-V14-F1ZNI-EM/SJB;31.10.2026;30.04.2027;e	
1422663	;CUC-V14-C1ZNI-T/R4E8;1422661	;CUC-V14-C1ZNI-S/R4E8;31.10.2026;30.04.2027;e	
1422662	;CUC-V14-C1ZNI-B/R4E8;1422661	;CUC-V14-C1ZNI-S/R4E8;31.10.2026;30.04.2027;e	
1422677	;CUC-V14-C1ZNI-B/R4E8;10;1422661	;CUC-V14-C1ZNI-S/R4E8;31.10.2026;30.04.2027;e	
1422667	;CUC-V14-C1ZNI-T/R4P8;1422664	;CUC-V14-C1ZNI-S/R4P8;31.10.2026;30.04.2027;e	
1422672	;CUC-V14-C1ZNI-B/R4P8;10;1422665	;CUC-V14-C1ZNI-B/R4P8;31.10.2026;30.04.2027;e	
1032275	;CUC-PPC-C2ZNI-SX/24FKP5:FCWO;1425514	;CUC-PPC-C2ZNI-SX/24FK	
1404210	;VS-PPC-C1-SCRJ-POBK-PG9-A3C-SI;1608045	;VS-PPC-C1-SCRJ-MNNA-I	
1404142	;VS-PPC-C1-RJ45-POBK-PG9-4Q5-OL;1608126	;VS-PPC-C1-RJ45-POBK-F	
1413297	;NBC-P2RM/2		
1417294	;VS-08-RJ45-5-Q/IP67 TIA568A;1656990	;VS-08-RJ45-5-Q/IP67;31.10.2026;30.04.2027;e	
1401301	;VS-PP-F-SCRJ LUE;1658121	;VS-PP-F-SCRJ;31.10.2026;30.04.2027;e	
1018526	;FOC-17P12-17P12-GL02/10;1792567	;FOC-17P12-17P12-GL02/10-T;31.10.2026;30.04.2027;e	
1018559	;FOC-17P12-17P12-GL02/90;1807793	;FOC-17P12-17P12-GL02/90-T;31.10.2026;30.04.2027;e	
1018557	;FOC-17P12-17P12-GL02/80;1807796	;FOC-17P12-17P12-GL02/80 -T;31.10.2026;30.04.2027;e	
1018556	;FOC-17P12-17P12-GL02/70;1807797	;FOC-17P12-17P12-GL02/70-T;31.10.2026;30.04.2027;e	
1018494	;FOC-17P12-17P12-GL02/5;1807805	;FOC-17P12-17P12-GL02/5 -T;31.10.2026;30.04.2027;e	
1019181	;FOC-17P12-17P12-GL02/20;1807810	;FOC-17P12-17P12-GL02/20-T;31.10.2026;30.04.2027;e	
1018560	;FOC-17P12-17P12-GL02/100;1807812	;FOC-17P12-17P12-GL02/100-T;31.10.2026;30.04.2027;e	
1018567	;FOC-17S12-LCD6-GF02/2;1807815	;FOC-17S12-LCD6-GF02/2-T;31.10.2026;30.04.2027;e	
1018568	;FOC-FR19:1U-17S12-LCD6-OM1;1807821	;FOC-FR19:1U-17S12-LCD6-(	
1018571	;FOC-MODUL:3U-17S12-LCD6-OM1;1807823	;FOC-MODUL:3U-17S12-LC	
1403374	;VS-M12FSBP-IP20-94C-LI/1		

1412453	;NBC-R4RC/0	
1141117	;NBC-R4BQ/1	
1203270	;NBC-R4BQ/0	
1203271	;NBC-R4BQ/1	
1267941	;NBC-R4BQ/0	
1141118	;NBC-R4BQ/1	
1416907	;VS-IP20-IP20-94B-LI/91;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2706
1408932	;NBC-R4AC/2	
1408929	;NBC-R4AC/1	
1394242	;NBC-R4AC/43	
1394241	;NBC-R4AC/33	
1394229	;NBC-R4AC/13	
1394239	;NBC-R4AC/23	
1657782	;RDM-SCRJ-KS-9005;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1657779	;RDM-SCRJ-T-IP67-9005-OLOGO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1573141	;VS-PPC-F1-RJ45-MNNA-1R-F-RDM;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1404781	;VS-PPC-C1-PC67-POBK SET SI/100;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1032393	;CUC-V14-A2RBK-PC:5 S01;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1412347	;NBC-P2RM/2	
1413296	;NBC-P2RM/10	
1064635	;CUC-V14-P1RBK/R4 WG:500 E02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1064633	;CUC-V14-P2RBK/24 WG:500 E02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1657847	;VS-PPC-F1-RJ45-P0BK-1R-PHA;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1416192	;VS-PPC/ME-IP20-93C-LI/5	
1419175	;VS-PPC/PL-OE-93K-LI/5	
1416173	;VS-BU/PN-IP20-93B-LI/2	
1408947	;NBC-R4QC/1	
1408941	;NBC-R4RC/1	
1413492	;VS-PPC/ME-PPC/ME-94C-LI/10	
1423084	;VS-IP20-IP20/LG-94B-LI/2	
1412943	;VS-PPC/ME-IP20-94C-LI/2	
1412736	;VS-PPC/ME-OE-94C-LI/2	
1412024	;VS-PPC/PL-IP20-94B-LI/5	
1408963	;NBC-R4RC/10	
1408967	;NBC-R4QC/10	
1415526	;VS-IP67/B-IP20-94F-LI/5	
1415885	;VS-PPC/ME-PPC/ME-94F-LI/5	
1415298	;VS-IP67-OE-94F-LI/5	
2744827	;FL CAT5 HEAVY CONF/;	::31.10.2026;30.04.2027;eCl@ss 13.0: 270603
2744843	;FL CAT5 FLEX CONF/;	::31.10.2026;30.04.2027;eCl@ss 13.0: 270603
2891327	;FL PLUG GUARD KEY;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744020
2891712	;FL PLUG GUARD RD;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744020
2891819	;FL PLUG GUARD WH;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744020
2891615	;FL PLUG GUARD GN;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744020
2891220	;FL PORT GUARD;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744020
1688667	;VS-08-A-RJ45/LP-4-IP 20;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1689970	;VS-25-ST-DSUB-5P;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1655438	;VS-25-BU-DSUB-5P-LH;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039

1689983	;VS-25-BU-DSUB-5P;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744030
1415756	;NBC-D5DM/1	
1415757	;NBC-D5DM/2	
1654840	;VS-09-A-GC-BLANK;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744021
1332073	;CUC-HDMI-J1ST-S/HAF-SMD;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1332071	;CUC-HDMI-J1ST-AH/HAF-SMD;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1332082	;NBC-HDMI-HAM/2	
1332079	;NBC-HDMI-HAM/1	
1332086	;NBC-HDMI-HAM/7	
1332084	;NBC-HDMI-HAM/5	
1332078	;NBC-HDMI-HAM/0	
1332081	;NBC-HDMI-HAM/1	
1332077	;NBC-HDMI-HAM/0	
1332083	;NBC-HDMI-HAM/3	
1717821	;FOC-17P24-17P24-GL03/2.1;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1717823	;FOC-17S24-ST:A24-GF03/3.5;	::31.10.2026;30.04.2027;eCl@ss 13.0
1717824	;FOC-17S24-ST:A24-GF03/3X;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1657601	;VS-SCRJ-POF-CONF;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2706100
1402191	;FOC-HCS-RUGGED-1014/...;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1
1719982	;FOC-LC:PA-LC:PA-OS2:D01/80;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1719981	;FOC-LC:PA-LC:PA-OS2:D01/15;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1041820	;FOC-I-D1PGY-S/MPAGC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1917
1041840	;FOC-I-D1PGY-S/MPBGC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1917
1407019	;FOC-TOOL-CERAMIC-BLADE;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1414104	;FOC-TOOL-CLEANINGWIPE;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1
1414105	;FOC-TOOL-MARKER BK;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1917
1414098	;FOC-TOOL-LIGHTSOURCE-650;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1406995	;FOC-TOOL-DISPENSER;	::31.10.2026;30.04.2027;eCl@ss 13.0: 1917
1334222	;FOC-CAGE:SFP/SFP+:1X4:PI;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1041881	;NBC-PP-F1PWH:10;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1041860	;NBC-PP-P1PGY:10;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2744039
1419182	;VS-V1-C-RJ45-MNNA-PG9-8-I-5-S;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1419185	;VS-V1-F-RJ45-MNNA-1-C-S-JI-S;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1419184	;VS-V1-F-RJ45-MNNA-1-C-S-JJ-S;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1419183	;VS-V1-C-PC-POBK;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27440208
1419186	;VS-V1-F-PC-POBK;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27440208
1652402	;VS-08-A-RJ45/MOD-1-IP67-SETLSA;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1688654	;VS-08-A-RJ45/LP-2-IP 20;	::31.10.2026;30.04.2027;eCl@ss 13.0: 274
1655742	;VS-04-2X2X26C7/7-67A/OE/1	
1655768	;VS-04-2X2X26C7/7-67A/OE/5	
1655755	;VS-04-2X2X26C7/7-67A/OE/2	
1653883	;VS-04-2X2X26C7/7-67A/67B/5	
1653870	;VS-04-2X2X26C7/7-67A/67B/2	
1653906	;VS-04-2X2X26C7/7-67A/SDB/5	
1653919	;VS-04-2X2X26C7/7-67B/SDA/2	
1653922	;VS-04-2X2X26C7/7-67B/SDA/5	
1653867	;VS-04-BUB-FK-F/IP67;	::31.10.2026;30.04.2027;eCl@ss 13.0: 274403
1653854	;VS-04-BUA-FK-F/IP67;	::31.10.2026;30.04.2027;eCl@ss 13.0: 274403

1563193	;VS-04-SCHLITTEN-USB;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27440
1464014	;CUC-V14-C1ZNI-S/R4IV8;	::31.10.2026;30.04.2027;eCl@ss 13.0: 274
1657889	;VS-PPC-F1-SCRJ-POBK-1RP;	::31.10.2026;30.04.2027;eCl@ss 13.0: 2
1137044	;VS-WASHER-3	
1413989	;CUC-V14-A1ZNI-S180;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27440
1417858	;NBC-M12MS/1	
1412976	;NBC-M12FR/3	
1412401	;NBC-M12FS/1	
1406247	;VS-M12FSBP-IP67-93E-LI/2	
1406399	;VS-M12FSBP-IP67/B-93E-LI/2	
1221641	;NBC-M12FSBPS-RJ45S-93B/0	
1423350	;NBC-FSDBP-PG9/0	
1418713	;NBC-MSDBP/1	
1413493	;NBC-FSDBPS/0	
1420603	;NBC-FSDBP/0	
1274876	;NBC-R4AC/0	
1274882	;NBC-DSUB09M/0	
1274881	;NBC-FS/2	
1415041	;Q2-MUTTER16-RND-OL-BK R03;	::31.10.2026;30.04.2027;eCl@ss 13.
1523566	;RDM-08-SD-F VPE500;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27440
1408001	;VS-PPC-C1-PC67-MNNA P01;	::31.10.2026;30.04.2027;eCl@ss 13.0:
1413295	;NBC-P2RM/5	
1404359	;VS-MSTBAH 2	
1445800	;VS-M12FSBP-IP20-94B-LI/5	
1423476	;NBC-MSDBP/0	

t.Bez.;Last Order;Last Shipment;Bemerkung
31.10.2026;30.04.2027;eCl@ss 13.0: 27061003
1.10.2026;30.04.2027;eCl@ss 13.0: 27061003
OM2-PT9;31.10.2026;30.04.2027;eCl@ss 13.0: 19170113
OM2-PT9;31.10.2026;30.04.2027;eCl@ss 13.0: 19170113
Cl@ss 13.0: 27460201
J4.2027;eCl@ss 13.0: 27460201
24;1227558 ;NBC-R4OC/0
0-93E/R4AC;1247639 ;NBC-R4ACS-R4ACS-IE8/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060
13-94B/R4AC;1247639 ;NBC-R4ACS-R4ACS-IE8/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 2706
75-94B/R4AC;1247639 ;NBC-R4ACS-R4ACS-IE8/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 2706
2027;eCl@ss 13.0: 27440208
2026;30.04.2027;eCl@ss 13.0: 21049090
0;1407725 ;VS-IP67-OE-94B-LI/5
J.04.2027;eCl@ss 13.0: 27440290
0.04.2027;eCl@ss 13.0: 27440290
1.10.2026;30.04.2027;eCl@ss 13.0: 27440290
0;1407932 ;VS-IP67-IP20-94B-LI/5
0-94B/R4MC;1411846 ;NBC-R4MC-R4MC-IE8/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 270603
0-94B/R4MC;1411846 ;NBC-R4MC-R4MC-IE8/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 270603
0;1411863 ;NBC-R4AC-R4RC-PN4/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;1411864 ;NBC-R4AC-R4QC-PN4/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-93B/R4QC;1411867 ;NBC-R4QC-R4QC-PN4/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060
0-93B/R4QC;1411867 ;NBC-R4QC-R4QC-PN4/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060
0-93B/R4QC;1411867 ;NBC-R4QC-R4QC-PN4/.../...;31.10.2026;30.04.2027;eCl@ss 13.0: 27060
026;30.04.2027;eCl@ss 13.0: 27440210
30.04.2027;eCl@ss 13.0: 27440290
;30.04.2027;eCl@ss 13.0: 27440290
I26;30.04.2027;eCl@ss 13.0: 27440290
30.04.2027;eCl@ss 13.0: 27440290
I26;30.04.2027;eCl@ss 13.0: 27440290
P5:FC;31.10.2026;30.04.2027;eCl@ss 13.0: 27440114
P9G-A3C-C;31.10.2026;30.04.2027;eCl@ss 13.0: 27440290
P9G-4Q5;31.10.2026;30.04.2027;eCl@ss 13.0: 27440290
0-1020/P2RM B02;1609206 ;VS-P1220-P1220-C1020/...;31.10.2026;30.04.2027;eCl@ss 13.0: 27
I6;30.04.2027;eCl@ss 13.0: 27440390
Pss 13.0: 19170113
1.10.2026;30.04.2027;eCl@ss 13.0: 27061003
1.10.2026;30.04.2027;eCl@ss 13.0: 27061003
L.10.2026;30.04.2027;eCl@ss 13.0: 27061003
1.10.2026;30.04.2027;eCl@ss 13.0: 27061003
0.2026;30.04.2027;eCl@ss 13.0: 27061003
1.10.2026;30.04.2027;eCl@ss 13.0: 27061003
31.10.2026;30.04.2027;eCl@ss 13.0: 27061003
2026;30.04.2027;eCl@ss 13.0: 27060307
OM1-T;31.10.2026;30.04.2027;eCl@ss 13.0: 19170113
CD6-OM1-T;31.10.2026;30.04.2027;eCl@ss 13.0: 19170113
0; ;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

6-93B/R4RC B02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
7-937/R4BQ-CO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
8-937/R4BQ-CO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-937/R4BQ-CO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
54-937/R4BQ-CO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
2-937/R4BQ-CO;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
i0307	
0-94B/F4AQ B02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/F4AQ B02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4RC T06;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4RC T06;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4RC T06;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4RC T06;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
i2	
}.0: 27440392	
13.0: 27440210	
s 13.0: 27061801	
7440290	
0-1020/OE B02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27061801
0-1020 B02;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
l3.0: 27440290	
.3.0: 27440290	
0: 27440210	
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-93E/R4QC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-93E/R4RC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
5;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4RC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-94B/R4QC;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
i307	
07	
92	
i8	
08	
i8	
40210	
2	
0302	

5-920/D5DF E01;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
5-920/D5DM E01;	::31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

27460201

0-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
5-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
5-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
5-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
3-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307
0-PVC/HAM;	;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

$$\vdots$$

27061803

.0:

.0:

70116

70116

21049090

.9170192

0192

0: 19170192

0192

27440392

0

)

13.0: 27440290

.0: 27440109

.0: 27440109

;

; 13.0: 27440392

40392

[illegible]

390

390

0192

l40290

27440210

2 B04; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 23071590

210

5-971/R4AQ VR; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

5-971/R4AQ VR; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

5-971/R4AQ VR; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

0; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

0; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

12; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

5-93E/R4AC; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

0-937/R4AQ; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

33-93B/R4ACR; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

25-937/R4AQ; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

3-93T/DSUB09F S10; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

2-93T/DSUB09F S10; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

0-93T/DSUB09F S10; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

.0: 27440192

392

27440208

0-1020 B02; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

5/ 5-GB-5

0 HDM; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

5-93E/R4AC; ;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440103

3-BC5/R4OC;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

0307

0307

0307

0;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

0;31.10.2026;30.04.2027;eCl@ss 13.0: 27060307

07

07

307

307

307

'060307

08-BKA-SI;

;;31.10.2026;30.04.2027;eCl@ss 13.0: 27440390

Kunde;Name 1;Name 2;Name 3;Name 4;Straße;Postleitzahl;Stadt;Phoenix Contact Art.Nr.;Phoenix Contact Art.B
49786 ;TTI

ez.;Ihre Materialnr.;Phoenix Contact Alternativ-Art.Nr.;Phoenix Contact Alternativ-Art.Bez.;Last-Order
Inc.;;;Ganghoferstraße 34;82216;Maisach;1332078 ;NBC-HDMI-HAM/0

;Last-Shipment;Menge 2024 ST;Menge 2025 ST;Menge 2026 ST;AE-Menge 2026 ST
5-PVC/HAM;PHX1332078;;31.10.2026;30.04.2027;;;40 ST;40 ST

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;
1414106;FOC-SC-LC-OM4-LS-CABLE/3; ; ;1115599;FOC-LC:PA-SC:PA-OM4:D01/3;27061003;
1414107;FOC-SC-LC-OS2-LS-CABLE/3;;;1115616;FOC-LC:PA-SC:PA-OS2:D01/3;27061003;
1145397;FOC-FDX20-FR19-STD24-OM2-PT9;;;1145407;FOC-FDX20-FR19-SCD24-OM2-PT9;19170113;
1145416;FOC-FDX20-FR19-LCD12-OM2-PT9;;;1145408;FOC-FDX20-FR19-SCD12-OM2-PT9;19170113;
1187028;SPE-STRM-90 W01;;;1163797;SPE-T1-STRM-90;27460201;
1292763;SPE-STRM-90-LED W01;;;1215778;SPE-T1-STRM-90-LED;27460201;
2700301;FL CAT5 PATCH 0
1422639;NBC-R4AC/45
1422790;NBC-R4AC/0
1422833;NBC-R4AC/1
1410447;CUC-V14-P2PBK H01;;;1405329;VS-PPC-F2-PC-POBK;27440208;
1414100;FOC-TOOL-STRIPPING-FA-2;;;1407016;FOC-TOOL-STRIPPING-T-1;21049090;
1407754;VS-IP67/B-OE-94B-LI/5
1408028;FOC-V14-C1ZNI-T/SJFP;;;1407896;FOC-V14-C1ZNI-S/SJFP;27440290;
1407902;FOC-V14-C1ZNI-B/SJFP;;;1407896;FOC-V14-C1ZNI-S/SJFP;27440290;
1404197;VS-PPC-C1-SCRJ-POBK-PG9-A4D-SI;;;1407896;FOC-V14-C1ZNI-S/SJFP;27440290;
1407961;VS-IP67/B-IP20-94B-LI/5
1408956;NBC-R4MC/2
1408955;NBC-R4MC/1
1416138;VS-PPC/ME-IP20-93B-LI/5
1416141;VS-PPC/PL-IP20-93B-LI/5
1408978;NBC-R4QC/1
1408980;NBC-R4QC/10
1408979;NBC-R4QC/2
1405235;VS-PPC-F1-SCRJ-MNNA-1C-F;;;1413964;FOC-V14-F1ZNI-EM/SJB;27440210;
1422663;CUC-V14-C1ZNI-T/R4E8;;;1422661;CUC-V14-C1ZNI-S/R4E8;27440290;
1422662;CUC-V14-C1ZNI-B/R4E8;;;1422661;CUC-V14-C1ZNI-S/R4E8;27440290;
1422677;CUC-V14-C1ZNI-B/R4E8:10;;;1422661;CUC-V14-C1ZNI-S/R4E8;27440290;
1422667;CUC-V14-C1ZNI-T/R4P8;;;1422664;CUC-V14-C1ZNI-S/R4P8;27440290;
1422672;CUC-V14-C1ZNI-B/R4P8:10;;;1422665;CUC-V14-C1ZNI-B/R4P8;27440290;
1032275;CUC-PPC-C2ZNI-SX/24FKP5:FCWO;;;1425514;CUC-PPC-C2ZNI-SX/24FKP5:FC;27440114;
1404210;VS-PPC-C1-SCRJ-POBK-PG9-A3C-SI;;;1608045;VS-PPC-C1-SCRJ-MNNA-PG9-A3C-C;27440290;
1404142;VS-PPC-C1-RJ45-POBK-PG9-4Q5-OL;;;1608126;VS-PPC-C1-RJ45-POBK-PG9-4Q5;27440290;
1413297;NBC-P2RM/2
1417294;VS-08-RJ45-5-Q/IP67 TIA568A;;;1656990;VS-08-RJ45-5-Q/IP67;27440390;
1401301;VS-PP-F-SCRJ LUE;;;1658121;VS-PP-F-SCRJ;19170113;
1018526;FOC-17P12-17P12-GL02/10;;;1792567;FOC-17P12-17P12-GL02/10-T;27061003;
1018559;FOC-17P12-17P12-GL02/90;;;1807793;FOC-17P12-17P12-GL02/90-T;27061003;
1018557;FOC-17P12-17P12-GL02/80;;;1807796;FOC-17P12-17P12-GL02/80 -T;27061003;
1018556;FOC-17P12-17P12-GL02/70;;;1807797;FOC-17P12-17P12-GL02/70-T;27061003;
1018494;FOC-17P12-17P12-GL02/5;;;1807805;FOC-17P12-17P12-GL02/5 -T;27061003;
1019181;FOC-17P12-17P12-GL02/20;;;1807810;FOC-17P12-17P12-GL02/20-T;27061003;
1018560;FOC-17P12-17P12-GL02/100;;;1807812;FOC-17P12-17P12-GL02/100-T;27061003;
1018567;FOC-17S12-LCD6-GF02/2;;;1807815;FOC-17S12-LCD6-GF02/2-T;27060307;
1018568;FOC-FR19:1U-17S12-LCD6-OM1;;;1807821;FOC-FR19:1U-17S12-LCD6-OM1-T;19170113;
1018571;FOC-MODUL:3U-17S12-LCD6-OM1;;;1807823;FOC-MODUL:3U-17S12-LCD6-OM1-T;19170113;
1403374;VS-M12FSBP-IP20-94C-LI/1

1412453;NBC-R4RC/0
1141117;NBC-R4BQ/1
1203270;NBC-R4BQ/0
1203271;NBC-R4BQ/1
1267941;NBC-R4BQ/0
1141118;NBC-R4BQ/1
1416907;VS-IP20-IP20-94B-LI/91;;;;;27060307;
1408932;NBC-R4AC/2
1408929;NBC-R4AC/1
1394242;NBC-R4AC/43
1394241;NBC-R4AC/33
1394229;NBC-R4AC/13
1394239;NBC-R4AC/23
1657782;RDM-SCRJ-KS-9005;;;;;27440392;
1657779;RDM-SCRJ-T-IP67-9005-OLOGO;;;;;27440392;
1573141;VS-PPC-F1-RJ45-MNNA-1R-F-RDM;;;;;27440210;
1404781;VS-PPC-C1-PC67-POBK SET SI/100;;;;;27061801;
1032393;CUC-V14-A2RBK-PC:5 S01;;;;;27440290;
1412347;NBC-P2RM/2
1413296;NBC-P2RM/10
1064635;CUC-V14-P1RBK/R4 WG:500 E02;;;;;27440290;
1064633;CUC-V14-P2RBK/24 WG:500 E02;;;;;27440290;
1657847;VS-PPC-F1-RJ45-P0BK-1R-PHA;;;;;27440210;
1416192;VS-PPC/ME-IP20-93C-LI/5
1419175;VS-PPC/PL-OE-93K-LI/5
1416173;VS-BU/PN-IP20-93B-LI/2
1408947;NBC-R4QC/1
1408941;NBC-R4RC/1
1413492;VS-PPC/ME-PPC/ME-94C-LI/10
1423084;VS-IP20-IP20/LG-94B-LI/2
1412943;VS-PPC/ME-IP20-94C-LI/2
1412736;VS-PPC/ME-OE-94C-LI/2
1412024;VS-PPC/PL-IP20-94B-LI/5
1408963;NBC-R4RC/10
1408967;NBC-R4QC/10
1415526;VS-IP67/B-IP20-94F-LI/5
1415885;VS-PPC/ME-PPC/ME-94F-LI/5
1415298;VS-IP67-OE-94F-LI/5
2744827;FL CAT5 HEAVY CONF/;;;;;27060307;
2744843;FL CAT5 FLEX CONF/;;;;;27060307;
2891327;FL PLUG GUARD KEY;;;;;27440192;
2891712;FL PLUG GUARD RD;;;;;27440208;
2891819;FL PLUG GUARD WH;;;;;27440208;
2891615;FL PLUG GUARD GN;;;;;27440208;
2891220;FL PORT GUARD;;;;;27440208;
1688667;VS-08-A-RJ45/LP-4-IP 20;;;;;27440210;
1689970;VS-25-ST-DSUB-5P;;;;;27440302;
1655438;VS-25-BU-DSUB-5P-LH;;;;;27440302;

1689983;VS-25-BU-DSUB-5P;;;;;27440302;
1415756;NBC-D5DM/1
1415757;NBC-D5DM/2
1654840;VS-09-A-GC-BLANK;;;;;27440210;
1332073;CUC-HDMI-J1ST-S/HAF-SMD;;;;;27460201;
1332071;CUC-HDMI-J1ST-AH/HAF-SMD;;;;;27460201;
1332082;NBC-HDMI-HAM/2
1332079;NBC-HDMI-HAM/1
1332086;NBC-HDMI-HAM/7
1332084;NBC-HDMI-HAM/5
1332078;NBC-HDMI-HAM/0
1332081;NBC-HDMI-HAM/1
1332077;NBC-HDMI-HAM/0
1332083;NBC-HDMI-HAM/3
1717821;FOC-17P24-17P24-GL03/2.1;;;;;
1717823;FOC-17S24-ST:A24-GF03/3.5;;;;;
1717824;FOC-17S24-ST:A24-GF03/3X;;;;;
1657601;VS-SCRJ-POF-CONF;;;;;27061002;
1402191;FOC-HCS-RUGGED-1014/...;;;;;27061803;
1719982;FOC-LC:PA-LC:PA-OS2:D01/80;;;;;
1719981;FOC-LC:PA-LC:PA-OS2:D01/15;;;;;
1041820;FOC-I-D1PGY-S/MPAGC;;;;;19170116;
1041840;FOC-I-D1PGY-S/MPBGC;;;;;19170116;
1407019;FOC-TOOL-CERAMIC-BLADE;;;;;21049090;
1414104;FOC-TOOL-CLEANINGWIPE;;;;;19170192;
1414105;FOC-TOOL-MARKER BK;;;;;19170192;
1414098;FOC-TOOL-LIGHTSOURCE-650;;;;;19170192;
1406995;FOC-TOOL-DISPENSER;;;;;19170192;
1334222;FOC-CAGE:SFP/SFP+:1X4:PI;;;;;27440392;
1041881;NBC-PP-F1PWH:10;;;;;27440390;
1041860;NBC-PP-P1PGY:10;;;;;27440390;
1419182;VS-V1-C-RJ45-MNNA-PG9-8-I-5-S;;;;;27440290;
1419185;VS-V1-F-RJ45-MNNA-1-C-S-JI-S;;;;;27440109;
1419184;VS-V1-F-RJ45-MNNA-1-C-S-JJ-S;;;;;27440109;
1419183;VS-V1-C-PC-POBK;;;;;27440208;
1419186;VS-V1-F-PC-POBK;;;;;27440208;
1652402;VS-08-A-RJ45/MOD-1-IP67-SETLSA;;;;;27440392;
1688654;VS-08-A-RJ45/LP-2-IP 20;;;;;27440392;
1655742;VS-04-2X2X26C7/7-67A/OE/1
1655768;VS-04-2X2X26C7/7-67A/OE/5
1655755;VS-04-2X2X26C7/7-67A/OE/2
1653883;VS-04-2X2X26C7/7-67A/67B/5
1653870;VS-04-2X2X26C7/7-67A/67B/2
1653906;VS-04-2X2X26C7/7-67A/SDB/5
1653919;VS-04-2X2X26C7/7-67B/SDA/2
1653922;VS-04-2X2X26C7/7-67B/SDA/5
1653867;VS-04-BUB-FK-F/IP67;;;;;27440390;
1653854;VS-04-BUA-FK-F/IP67;;;;;27440390;

1563193;VS-04-SCHLITTEN-USB;;;;;27440192;
1464014;CUC-V14-C1ZNI-S/R4IV8;;;;;27440290;
1657889;VS-PPC-F1-SCRJ-POBK-1RP;;;;;27440210;
1137044;VS-WASHER-3
1413989;CUC-V14-A1ZNI-S180;;;;;27440210;
1417858;NBC-M12MS/1
1412976;NBC-M12FR/3
1412401;NBC-M12FS/1
1406247;VS-M12FSBP-IP67-93E-LI/2
1406399;VS-M12FSBP-IP67/B-93E-LI/2
1221641;NBC-M12FSBPS-RJ45S-93B/0
1423350;NBC-FSDBP-PG9/0
1418713;NBC-MSDBP/1
1413493;NBC-FSDBPS/0
1420603;NBC-FSDBP/0
1274876;NBC-R4AC/0
1274882;NBC-DSUB09M/0
1274881;NBC-FS/2
1415041;Q2-MUTTER16-RND-OL-BK R03;;;;;27440192;
1523566;RDM-08-SD-F VPE500;;;;;27440392;
1408001;VS-PPC-C1-PC67-MNNA P01;;;;;27440208;
1413295;NBC-P2RM/5
1404359;VS-MSTBAH 2
1445800;VS-M12FSBP-IP20-94B-LI/5
1423476;NBC-MSDBP/0

24;;;1227558;NBC-R4OC/0
0-93E/R4AC;;;1247639;NBC-R4ACS-R4ACS-IE8/.../...;27060307;
13-94B/R4AC;;;1247639;NBC-R4ACS-R4ACS-IE8/.../...;27060307;
75-94B/R4AC;;;1247639;NBC-R4ACS-R4ACS-IE8/.../...;27060307;

3-BC5/R4OC;27060307;

0;;;1407725;VS-IP67-OE-94B-LI/5
0;27060307;

0;;;1407932;VS-IP67-IP20-94B-LI/5
0-94B/R4MC;;;1411846;NBC-R4MC-R4MC-IE8/.../...;27060307;
0-94B/R4MC;;;1411846;NBC-R4MC-R4MC-IE8/.../...;27060307;
0;;;1411863;NBC-R4AC-R4RC-PN4/.../...;27060307;
0;;;1411864;NBC-R4AC-R4QC-PN4/.../...;27060307;
0-93B/R4QC;;;1411867;NBC-R4QC-R4QC-PN4/.../...;27060307;
0-93B/R4QC;;;1411867;NBC-R4QC-R4QC-PN4/.../...;27060307;
0-93B/R4QC;;;1411867;NBC-R4QC-R4QC-PN4/.../...;27060307;

0;27060307;

0-1020/P2RM B02;;;1609206;VS-P1220-P1220-C1020/...;27060307;

0;;;;;27440103;

6-93B/R4RC B02;;;;;27060307;
7-937/R4BQ-CO;;;;;27060307;
8-937/R4BQ-CO;;;;;27060307;
0-937/R4BQ-CO;;;;;27060307;
54-937/R4BQ-CO;;;;;27060307;
2-937/R4BQ-CO;;;;;27060307;

0-94B/F4AQ B02;;;;;27060307;
0-94B/F4AQ B02;;;;;27060307;
0-94B/R4RC T06;;;;;27060307;
0-94B/R4RC T06;;;;;27060307;
0-94B/R4RC T06;;;;;27060307;
0-94B/R4RC T06;;;;;27060307;

0-1020/OE B02;;;;;27061801;
0-1020 B02;;;;;27060307;

0;;;;;27060307;
0;;;;;27060307;
0;;;;;27060307;
0-93E/R4QC;;;;;27060307;
0-93E/R4RC;;;;;27060307;
0;;;;;27060307;
5;;;;;27060307;
0;;;;;27060307;
0;;;;;27060307;
0;;;;;27060307;
0-94B/R4RC;;;;;27060307;
0-94B/R4QC;;;;;27060307;
0;;;;;27060307;
0;;;;;27060307;
0;;;;;27060307;

5-920/D5DF E01,,,,,27060307;
5-920/D5DM E01,,,,,27060307;

0-PVC/HAM,,,,,27060307;
0-PVC/HAM,,,,,27060307;
5-PVC/HAM,,,,,27060307;
0-PVC/HAM,,,,,27060307;
5-PVC/HAM,,,,,27060307;
5-PVC/HAM,,,,,27060307;
3-PVC/HAM,,,,,27060307;
0-PVC/HAM,,,,,27060307;

[illegible]

2 B04,,,,,23071590;

5-971/R4AQ VR,,,,,27060307;

5-971/R4AQ VR,,,,,27060307;

5-971/R4AQ VR,,,,,27060307;

0,,,,,27440103;

0,,,,,27440103;

12,,,,,27440103;

5-93E/R4AC,,,,,27440103;

0-937/R4AQ,,,,,27440103;

33-93B/R4ACR,,,,,27440103;

25-937/R4AQ,,,,,27440103;

3-93T/DSUB09F S10,,,,,27060307;

2-93T/DSUB09F S10,,,,,27060307;

0-93T/DSUB09F S10,,,,,27060307;

0-1020 B02,,,,,27060307;

5/ 5-GB-5

0 HDM,,,,,27060307;

5-93E/R4AC,,,,,27440103;

08-BKA-SI,,,,,27440390;